

## For Banksmeadow Transfer Terminal

Document Code: PLA-NSW-XXX-XXX-1

Date: 23.06.2016

Veolia Australia and New Zealand NSW Resource Recovery – Banksmeadow Transfer Terminal Cnr Unwin and Shirley Streets Rosehill NSW 2142 www.veolia.com.au

Tel: 02 9841 2500



## **QUALITY INFORMATION**

#### **Document Revision Register**

Rev	Revision Details	Prepared By	Review By	Authorised By	Date
0	Initial draft for internal review	R Bachu NSW Environment Officer			17 Feb 2016
0	Final Draft	R Bachu NSW Environment Officer	M Chilcott Director – Linchpin Environmental Pty Ltd	C Hodgkiss General Manager Strategic Planning, Development and Projects	15 Apr 2016
1	Final	R Bachu NSW Environment Officer	A Brar Environmental Planner	C Hodgkiss General Manager Strategic Planning, Development and Projects	23 Jun 2016



### Contents

Quality In	formation		2
Definition	s/Abbreviat	ions	4
Section 1	Introductio	n	5
	1.1 1.2 1.3 1.4	Overview Scope and Objectives Legal and Other Requirements Stakeholder Consultation	5 6
Section 2	Goals of S	<i>N</i> LMP	11
	2.1	Roles and Responsibilities	11
Section 3	Existing Er	vironment and Operational Impacts	12
	3.1 3.2	Existing Environment Predicted Soil, Water and Leachate Impacts	
Section 4	Soil, Water	and LeachAte management Measures	18
	4.1 4.2 4.3 4.4	Erosion and Sediment Control Plan Stormwater Management Plan Leachate Management Plan Other control measures	18 20
Section 5	Soil, Water	and Leachate Monitoring and Reporting	22
	5.1 5.2 5.3 5.4	Monitoring Program Performance Reporting and Review Exceedances and Corrective Actions Publishing of Monitoring Data	24 24
Section 6	Surface Wa	ater, Groundwater and Leachate Response Plan	25
Section 7	References	s	29
Appendic	es		30
Арреі Арреі Арреі Арреі	ndix Bndix Cndix Dndix Dndix E	Site Plans Stormwater Infrastructure Maintenance Schedule Hot Load Management Specification Baseline Water Data Long Term Environmental Management Plan Groundwater wells locations	31 32 33 34 35 36



Page 4 of 36 PLA-NSW-XXX-XXX-1 23.06.2016

Soil, Water and Leachate Management

### **Definitions/Abbreviations**

AEP	Annual Exceedance Probability		
ARTC	Australian Rail Track Corporation		
BTT	Banksmeadow Transfer Terminal		
BGL	Below Ground Level		
CEMP	Construction Environmental Management Plan		
EIS	Environmental Impact Statement		
ERP	Emergency Response Plan		
EPL	Environment Protection Licence		
GPT	Gross Pollutant Trap		
L	Litres		
ML	Megalitres		
NIMS	National Integrated Management System		
OEMP	Operational Environment Management Plan		
OSD	On Site Detention		
POEO	Protection of the Environment Operations (Act and Regulation)		
The Vault	Veolia's Incident and Compliance Management System		
SMCMA	Sydney Metropolitan Catchment Management Authority		
SWLMP	Soil Water and Leachate Management Plan		
Veolia	Veolia Australia and New Zealand		
WSUD	Water Sensitive Urban Design		



**SECTION 1** 

PLAN

Soil, Water and Leachate Management

#### INTRODUCTION

#### 1.1 Overview

Veolia Australia and New Zealand (Veolia) operates the Banksmeadow Transfer Terminal (BTT), which is located at 14 Beauchamp Road and 34-36 McPherson Street, Banksmeadow (refer to site plans in OEMP Appendix A).

The BTT facility has been approved receive up to 500,000 tonnes per annum (TPA) of waste (including 400,000 TPA of putrescible waste and 100,000 TPA of non putrescible waste) from within the Sydney Region. The waste will be containerised and loaded onto rail wagons for transportation by rail to the Woodlawn Eco Project Site (owned and operated by Veolia) in the Southern Tablelands (approximately 250 kilometres southwest of Sydney) for treatment, recycling and energy recovery.

The BTT includes the following infrastructure:

- An access road for waste trucks entering and exiting the facility from Beauchamp Road.
- Incoming and outgoing weighbridges to check the waste type and weight of the waste being delivered to the facility.
- An enclosed building for the unloading and handling of waste, with environmental controls such as dust suppression and odour control systems.
- A hardstand area for temporary storage and manoeuvring of full and empty sealed shipping containers prior to loading on to trains.
- Rail sidings for the loading of containers onto trains for rail transport to Woodlawn.

The NSW Department of Planning and Environment (DPE) assessed the State Significant development (SSD 5855) and granted Development Consent for the 'State Significant' development on 28 April 2015, in accordance with section 89 (e) of the *Environmental Planning and Assessment Act 1979* (EP&A Act).

In addition, an Environmental Protection Licence (EPL) has been issued under the *Protection of the Environment Operations Act 1997* (POEO Act) by the NSW Environment Protection Authority (EPA).

This Soil, Water and Leachate Management Plan (SWLMP) has been prepared in accordance with the requirements of the Conditions of Development Consent (the Consent Conditions) and the Environment Protection Licence (EPL) issued for the BTT. The SWLMP details control strategies for effective erosion and sediment control, conservation of water quality and management of groundwater, surface water and storm water during the operation of the BTT.

The SWMLP incorporates the Leachate Management Plan, Stormwater Management Plan and Surface Water, Groundwater and Leachate Response Plan.


#### 1.2 Scope and Objectives

The purpose of this SWLMP is to provide soil, water and leachate management procedures to form part of the BTT Operational Environmental Management Plan (OEMP), in accordance with the Consent Conditions, EPL, relevant legislation and as part of Veolia's National Integrated Management System (NIMS).

The OEMP is the working environmental management tool for the operation of the BTT, concentrating on key environmental issues, including supporting detailed plans for the management of water quality, waste, traffic, air quality, greenhouse gas, noise, landscape and vegetation and emergency response.

The objectives of the SWLMP are to:





Soil, Water and Leachate Management

- Provide a comprehensive plan for the management of soil, water and leachate management during operation of the BTT
- Protect water quality, by preventing storm and surface water flows impacting on sensitive receptors;
- Prevent surface water pollution from surface discharges of any contaminated water from the BTT; and
- Comply with the relevant regulatory requirements.

#### **1.3 Legal and Other Requirements**

The following regulatory framework applies to this SWLMP:

- Development Consent (DA SSD 5855) issued under the *Environmental Planning* and Assessment Act 1979
- Environment Protection Licence (EPL 20581) issued under the *Protection of the Environment Operations Act 1997* (POEO Act) and particularly the POEO (Clean Air) Regulation 2002

#### 1.3.1 Conditions of Development Consent

Consent conditions 9 to 13 of Schedule 3 relate to soil, water and leachate management; and in particular, Condition 10 requires the preparation and implementation of a Soil, Water and Leachate Management Plan. The requirements considered relevant to this SWLMP are detailed in Table 1.1 below.

#### **Table 1.1 Operation Consent Requirements**

Relevant Condition		
10	<ul> <li>The Applicant shall prepare and implement a Soil, Water and Leachate Management Plan for the Development in consultation with the City of Botany Bay Council, NOW and the EPA and to the satisfaction of the Secretary. This plan must be prepared and implemented by a suitably qualified and experienced person and be submitted for approval prior to commencement of construction.</li> <li>The plan must include:</li> <li>a site water balance that:         <ul> <li>identifies the source of all water collected or stored on site, including rainfall, stormwater and groundwater;</li> <li>includes details of all water use on site and any discharges; and</li> <li>describes the measures that will be implemented to minimise water use on site.</li> </ul> </li> </ul>	
10(a)		
10(b)	<ul> <li>an erosion and sediment control plan that: <ul> <li>is consistent with the requirements in the latest version of the Blue Book Volume 1 and Volume 2B;</li> <li>identifies the activities on site that could cause soil erosion and generate sediment; and</li> <li>describe the measures that will be implemented to: <ul> <li>minimise soil erosion and the transport of sediment to downstream waters, including the location, function and capacity of any erosion and sediment control structures and maintain these structures over time;</li> <li>ensure that any topsoil stockpiles on site are suitably managed to ensure that the topsoil in these stockpiles can be beneficially used in the proposed revegetation and rehabilitation of the site.</li> </ul> </li> </ul></li></ul>	Not applicable to operations
10(c)	<ul> <li>a leachate management plan that:</li> <li>includes final detailed design specifications of the leachate management and</li> </ul>	Refer to Section 4.3

Printed documents are uncontrolled versions. Check printed copies against the current electronic version for validity.





	collection system on site.	
10(d)	<ul> <li>a stormwater management plan that:</li> <li>is consistent with the guidance in the latest version of the Blue Book Volume 1 and Volume 2B;</li> <li>includes final detailed design specifications for the stormwater management and collection system; and</li> <li>demonstrates how the requirements of Condition C11 of this schedule has been addressed.</li> </ul>	
10(e)	<ul> <li>a surface water, groundwater and leachate monitoring program that includes:</li> <li>baseline data;</li> <li>details of the proposed monitoring network; and</li> <li>the parameters for testing and respective trigger levels for action under the surface water, groundwater and leachate response plan.</li> </ul>	
10(f)	<ul> <li>a surface water, groundwater and leachate response plan that:</li> <li>includes a protocol for the investigation, notification and mitigation of any exceedances of the respective trigger levels; and</li> <li>describes the measures that could be implemented to respond to any surface or groundwater contamination that may be caused by any development.</li> </ul>	Refer to Section 6

#### 1.3.2 <u>Mitigation Measures</u>

In addition, the operational mitigation measures appended to the Consent Conditions for soil, water and leachate management are presented below.

#### **Table 1.2 Operational Mitigation Measures Requirements**

	Mitigation Requirement	SWLMP Reference
Soils a	and contamination	
1	A site Environmental Management Plans (SEMP) would be prepared and implemented for the Keith Engineering land, with provisions for on-going regular inspection and maintenance of the capped contaminated soils. The SEMPs would be reviewed and approved by a NSW EPA accredited site auditor.	Noted and Refer Section 4.1
2	Appropriate mitigation measures for stormwater runoff detention would be implemented, reducing the risk of erosion and sedimentation as a result of excessive runoff.	N/A for operations
3	The diesel tank will be self-bunded and compliant with AS - 1940-2004 <i>The storage and handling of flammable and combustible liquids</i> . The diesel fuel tank and refuelling area would be appropriately bunded and all refuelling would take place within this area.	Refer Section 4.4
4	An Incident Response Plan (IRP) will be developed for operation of the site. The plan would specify the procedure to be followed in the event of a spill, including the notification requirements and use of absorbent material to contain the spill. A spill kit will be provided onsite at all times.	Refer ERP and Section 6
5	A refuelling procedure will be developed and implemented for all refuelling activities undertaken. Any fuel, lubricant, or hydraulic fluid spillages will be collected using absorbent material and the contaminated material disposed of to a licensed waste facility	Refer Section 4.4





Hydrology and Flooding		
2	2 The leachate management system will be designed to maintain separation between rainfall run-off and leachate at all times. A minimum 20 kL self-bunded tank will be provided for collection of leachate from the transfer terminal building and compactor area.	
3	The compactor areas will be fully covered to limit the generation of leachate. A to facilities the transport of leachate to the Woodlawn Eco-Project Site.	Refer Section 4.3
4	OSD will be provided onsite to achieve Botany Bay City Council's requirement of 20% AEP 'natural condition' detention and to offset the calculated flood storage volume of 810 m <sup>3</sup> .	Refer Section 4.2.1
5	WSUD measures will be included within the detailed design for the BTT and will include the provision of bioretention basins and oil and grease interceptors within the new drainage pits.	Refer Section 4.2
6	A 40 KL tank for stormwater storage will be provided beneath the terminal building for the purposes of washdown, toilet flushing and irrigation to minimise potable water demand at the facility.	Refer Section 4.2
7	All excess leachate from the BTT will be disposed of in accordance with legislative requirements, through either a trade waste agreement or pumped out and disposed of at an appropriately licensed facility.	Refer Section 4.3
8	The diesel fuel tank and refuelling area will be appropriately bunded. All refuelling will take place within this area.	Refer Section 4.4
9	An Incident Response Plan (IRP) will be developed for the Site and will form a sub-plan to the OEMP. The IRP will contain a 'spill response procedure'.	Refer Section 6 and ERP

#### 1.3.3 Environment Protection Licence

EPL No. 20581 stipulates the environmental obligations for Veolia under s120 of the POEO Act to make all efforts to control the pollution of water from the BTT.

Conditions E2 and E3 set out requirements in relation to the management of spills and other liquid discharges on site as detailed in Table 1.3 below.

Relevant Conditions			
E2.1	While the licensee's premises are being used for the purpose to which the licence relates, the licensee must:		
	(a) Clean up any spill, leak or other discharge of any waste(s) or other material(s) as soon as practicable after it becomes known to the licensee or to one of the licensee's employees or agents.		
	(b) In the event(s) that any liquid and non-liquid waste(s) is unlawfully deposited on the premises, such waste(s) must be removed and lawfully disposed of as soon as practicable or in accordance with any direction given by the EPA.	Noted. Refer Section 6	
	(c) Provide all monitoring data as required by the conditions of this licence or as directed by the EPA.		
E2.2	In the event of an earthquake, storm, fire, flood or any other event where it is reasonable to suspect that a pollution incident has occurred, is occurring or is liksely to occur, the licensee (whether or not the premises continue to	Refer to Section 6	

#### Table 1.3 Environment Protection Licence Requirements



#### Soil, Water and Leachate Management

be used for the purposes to which the licence relates) must:
(a) Make all efforts to contain all firewater on the licensee's premises;
(c) Make all efforts to contain any discharge, spill or run-off from the licensee's premises;
(d) Make all efforts to prevent flood water entering the licensee's premises;
(e) Remediate and rehabilitate any exposed areas of soil and/or waste;
(f) Lawfully dispose of all liquid and solid waste(s) stored on the premises that is not already securely disposed of;
(g) At the request of the EPA monitor groundwater beneath the licensee's premises and its potential to migrate from the licensee's premises;
(h) At the request of the EPA monitor surface water leaving the licensee's premises;

#### 1.4 Stakeholder Consultation

As part of an ongoing commitment to stakeholder engagement, Veolia has implemented a program of communication and consultation during the preparation of this SWLMP. Veolia has consulted with government agencies and other key stakeholders.

The key issues raised during consultation for soil, water and leachate impacts included accidental spills or leaks, flooding capacity and discharge levels and leachate contamination causing pollution on surrounding areas.

#### 1.4.1 <u>Government Bodies</u>

The following government bodies have been consulted with in relation the requirements of this SWLMP:

- NSW Department of Planning and Environment;
- NSW Environment Protection Authority;
- City of Botany Bay Council
- NSW Office of Water

#### 1.4.2 <u>Community</u>

Veolia aims to ensure that the local community remains informed of the progress of the project in a pro-active and responsive manner. Veolia's communication may include the following where applicable:

- public notices and announcements;
- meetings and correspondence with appropriate regulatory authorities; and
- discussions with adjoining land owners / neighbours who may be affected by the BTT.

The key objectives of the community focused communication and consultation program include:

- Educating stakeholders regarding key aspects of the BTT; and
- Informing community groups and neighbours to help Veolia understand concerns.

The following avenues provide availability of information about the BTT:

• Dedicated Veolia webpage:



http://www.veolia.com.au/sustainable-solutions/communitydevelopment/banksmeadow-transfer-terminal

• Community telephone line:

Location	Contact
BTT 24 hour feedback line	1800 298 981

- Dedicated email address:
   <u>banksmeadow@veolia.com au</u>
- Published monitoring data:

http://www.veolia.com.au/sustainable-solutions/environmental-compliance/nswenvironmental-monitoring-data

#### SECTION 2 GOALS OF SWLMP

The goals of this SWLMP are to:

• To confirm that, following construction of the BTT, all residual soil management issues have been addressed and confirm any on-going monitoring requirements for the facility with respect to soil management

To protect water quality, by preventing contaminated storm and surface water impacting on sensitive receptors;

- To prevent surface water pollution due to contaminated surface water discharges from the BTT;
- To confirm the detailed design of the leachate management and collection system on site; and
- To ensure that on-site systems for leachate management operate according to design and are maintained to ensure on-going effectiveness in managing all on-site leachates.

#### 2.1 Roles and Responsibilities

Responsibilities for implementation of this SWLMP are summarised in Table 2.1 below.

Action	Responsibility	Timing
Overall implementation of the SWLMP	Facility Manager	Ongoing
Induct site personnel on the site safety and environmental requirements of the SWLMP prior to commencing any work on site	Facility Manager or nominee	Commencement of operations and site inductions for new employees
Coordinate site environmental monitoring, compile reports and maintain internal records	Facility Manager or nominee	As per monitoring schedule
Identify Non Conformances and notify BTT Management/ Veolia Safety Health Environment Quality Representative	Facility Manager or nominee	As Required
Authorise and confirm the implementation of mitigation measures	Facility Manager or nominee	Annual
Training and communication	Facility Manager or nominee	Ongoing
Monitoring the effectiveness of the control measures	Facility Manager or nominee	As per monitoring schedule
Environmental compliance monitoring	Technical and Engineering Team	As per monitoring schedule

 Table 2.1
 Summaries of Responsibilities – SWLMP



Page: Page 12 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016

#### Soil, Water and Leachate Management

## SECTION 3 EXISTING ENVIRONMENT AND OPERATIONAL IMPACTS

#### 3.1 Existing Environment

The BTT site is located in the Springvale Drain catchment in a low-lying area approximately 800m from Botany Bay. The high level of urbanisation within the catchment has resulted in large areas of impervious surfaces, connecting them directly to waterways via stormwater infrastructure. Accordingly, the Botany Bay catchment generates approximately 292,435 megalitres (ML) of stormwater runoff each year.

Very little flow from external catchments enters the BTT as the site catchment is highly constrained by the following structures and developments:

- To the east the BTT is constrained by the Botany Industrial Park, which diverts stormwater to the south-east, away from the BTT.
- The Botany Goods Line to the east and north of the BTT is raised and would prevent the entry of stormwater onto the BTT.
- The Banksmeadow Recycling Centre located centrally to the BTT is bounded by retaining walls, which prevent the flow of stormwater onto the site, as it discharges directly into the drainage system connecting to McPherson Street.

#### 3.1.1 Soil and groundwater

The BTT EIS (Hyder, 2014) provided details regarding the soil and groundwater, which included the following description:

The soil of the BTT site are generally characterised as being highly disturbed to depths of at least 1 m, with the original soils having been removed or buried, which overlay either compacted mottled clay or transported fills. The disturbed nature of the soil is reflective of the history of industrial uses and development that has occurred in the area. Prior to development of the site, surface soils were likely to have been organic, peaty soils. However, most of this cover has been removed.

The adjacent Tuggerah soil type is typically characterised as having bleached loose sand to depths of over 100 cm, overlaying black soft sandy organic pan and brown soft sandy iron pan materials (Chapman and Murphy. 2004). These soil types are typically highly permeable, with low fertility, low pH and a permanently high water table.

An investigation of the BTT site (Douglas Partners, 2013; Douglas Partners, 2012) identified the soil profile within the site as follows:

- Surface soils, from 0.2 m to 2.4 m below ground level (BGL) comprised hardstand and fill material, that is predominantly crushed concrete and road based gravel,
- Between 2.4 m and 9.7 m BGL soils comprise alluvial sands, typically ranging from medium density to high density. The alluvial sands also contain thin layers of organic sand, silty sand and organic clay (peaty sand and peaty clay) with a high organic content and typically very loose to loose/soft and wet.
- Between 9.7 m and 12.9 m below ground level soils comprise hard clay.

The water table at the site occurs at variable depths across the site, ranging from 1.71 m BGL and greater than 5.14 m BGL. The site is located within the Botany Sands Aquifer and the 'Botany Sands Aquifer Interference zone'. The groundwater



levels within the Botany Sands Aquifer have been observed to range by up to 2 m (Hyder 2014).

#### 3.1.2 Catchments

The Civil Engineering Report (Costin Roe, 2015) provided the following definition of the regional catchment:

The site is located within the Springvale Drain catchment and, following discharge from the site into the local sub-catchment, stormwater flows are conveyed to the Springvale Drain, which is located some 250m to the west of the site. The Springvale Drain has an overall catchment area of approximately 246.7 Ha and travels south across parks, residential areas and industrial areas. The Springvale Drain consists of a series of open channels and underground culverts and pipes which convey stormwater runoff through the catchment to Botany Bay.

The site drains towards the existing kerb inlet pipe at the low point in McPherson Street. The low point is located at the cul-de-sac head of McPherson Street on the eastern site of the existing railway tracks. A contributing upstream external catchment with an area of approximately 12.84 Ha also drains towards the lowpoint in McPherson Street.

#### 3.1.3 **Flood Storage**

The BTT EIS (Hyder, 2014) notes the following regarding flood storage:

Flood modelling undertaken for the City of Botany Bay Council indicates that the peak flood depth at the BTT during the 1% annual exceedance probability (AEP) event is in the range of 0m - 0.5m, with peak flow velocities below 0.6m/s (BMT WBM, 2013), thus, flood hazard at the site is considered low.

This shows that even during 'extreme' events the flood is relatively minor. During any flood event that may affect the Springvale Drain and Botany Bay catchment any floodwater at the BTT would be classified as part of the 'flood fringe'.

#### 3.1.4 Water balance

A water balance was prepared as part of the BTT EIS (Hyder 2014) to describe the source of water collected or stored at the BTT, as well as the likely site demand and discharge limits associated with operation of the Proposal. It assessed whether water demand can be offset by water harvesting or water reuse strategies.

Water balance was calculated as follows:

Water demand - water supply=net water balance

This information has been used to design and construct the water management infrastructure that will:

- (i) achieve the storage capacity;
- (ii) comply with regulatory requirements; and

(iii) sustain on site water usage during the BTT operation stage, while minimising the use of potable water.

For the purposes of the water balance the demand portion of the balance was assumed to consist of any water usage where potable water quality wouldn't normally be. This included:



- Toilet flushing.
- Washdown water.

To offset these water demands rainwater harvesting was investigated and was calculated based on the transfer terminal building and office building roof areas, with a run-off coefficient of 0.95, to account for any run-off that may not reach the gutter system.

Average monthly rainfall was sourced from the Randwick Racecourse weather station.

The table below (drawn from Table 8-30 of the EIS [Hyder 2014]) provides a monthly summary of water demand and supply for non-potable water on the BTT site.

Month	Demand (kL)	Supply (kL)	Balance (kL)
Jan	71.11	420.42	349.30
Feb	64.23	465.97	401.73
Mar	71.11	518.75	447.63
Apr	68.82	443.49	374.67
Мау	71.11	463.34	392.23
Jun	68.82	571.90	503.08
Jul	71.11	295.90	224.79
Aug	71.11	320.86	249.75
Sep	68.82	223.11	154.29
Oct	71.11	287.44	216.33
Nov	68.82	346.84	278.02
Dec	71.11	269.94	198.83
TOTAL	837.28	4627.96	3790.65


#### Table 3.1 Monthly net water balance

It is noted that where there is a positive water balance this does not guarantee supply at every stage during the month. Rainfall variability and storage capacities would determine whether there is a positive water balance at any given time.

Figure 3.1, from the BTT EIS (Hyder 2014) provides the difference between the potential for water harvesting and water demand for the BTT over the course of a year.







#### Figure 3.1 Water supply vs. water demand

The water balance assessment concluded that the equivalent of 40 kL of rainwater storage would accommodate the non-potable water demand for the BTT operations.

#### 3.2 **Predicted Soil, Water and Leachate Impacts**

The EIS identified potential site contamination and water quality impacts and associated risks associated with the operation of the BTT.

Table 3.2 lists these impacts and risks. This risk assessment determined the level of mitigation required for those impacts.

Issue	Potential Impact	Source	Risk Ranking	Control required and reference, where applicable
Soils and groundwater contamination	BTT contamination and risk of human and environmental health risks from exposure.	The BTT site is located within the area of an Approved Voluntary Management Proposal (20101714) and Declaration of Remediation BTT (21074) and therefore must address SEPP 55.	Very High	No. Should any further excavation works be required that may encounter contaminated soil and groundwater at the facility, the BTT CEMP

#### Table 3.2 Soil and Water Impact Risk Rating



# Page:PageDocument:PLA-Date:23.06

Page 16 of 36 PLA-NSW-XXX-XXX-1 23.06.2016

#### Soil, Water and Leachate Management

				Construction Site Contamination Management Plan would be triggered.
	Discharge of contaminated groundwater from the BTT.	The BTT site is located within the Botany Sands aquifer Groundwater Extraction Exclusion Area, due to the high likelihood of groundwater contamination due to previous activities on adjoining sites.	Very High	No. Should any further excavation works be required that may encounter contaminated soil and groundwater at the facility, the BTT CEMP Construction Site Contamination Management Plan would be triggered.
Hydrology and flooding	Alterations to hydrology on-site and discharge levels from BTT, resulting in increased flood levels downstream.	The BTT operations would result in an increase in impervious surfaces at the site and consequently an increase in the stormwater runoff generated. This has the potential to cause flooding downstream of the BTT.	High	Yes Refer to Section 4.2
	Release of leachate from putrescible waste to stormwater causing pollution of surface water.	Putrescible waste handled at the BTT has the potential to generate leachate which, if not contained, has the potential to reach surface or groundwater and cause pollution.	High	Yes Refer to Section 4.3
	Flood impacts on-site from Springvale drain.	Modelling undertaken by Botany Bay City Council has identified the potential for portions of the BTT to be flood affected.	High	Yes Refer to Section 4.2

Based on this information, the following are the predicted impacts relate to soil contamination or water quality impacts at the BTT:

#### 3.2.1 Soils and groundwater

Soil contamination could occur through the use of oils, fuel, lubricants and other chemical substances required for the operation of vehicles, plant and machinery during within the BTT.

Accidental spills or leaks within the site and rail corridor have the potential to result in the transportation of contaminants into the surrounding environment including groundwater. This risk of soil contamination is highest in the maintenance area, where



the majority of chemicals would be stored, and associated with a diesel storage tank located in the maintenance area.

In the unlikely event that further excavations works are required within the BTT site, there would be a risk that the work may encounter contaminated soil and groundwater, including within the Botany Sands aquifer.

#### 3.2.2 Stormwater

Alterations to hydrology on-site, flood storage capacity and discharge levels from BTT could result in increased flood levels downstream. However, as discussed in Section 3.1.2, the catchment within the BTT site is highly constrained and very little stormwater flow from external catchments enters the BTT site.

Construction of the BTT has resulted in an increase in impervious surfaces within the site. Consequently there is a potential for an increase in the stormwater runoff generated onsite. This has the potential to cause additional stormwater flows downstream of the BTT. Modelling undertaken by the City of Botany Bay Council has also identified the potential for portions of the BTT to be at risk of being flood affected.

These constraints mean that stormwater drainage requirements on the BTT are largely independent of external flows and, but are dependent on the amount of rain falling directly on the property (refer to Stormwater Catchment Plan (CO12589.00-C40) in Appendix A).

#### 3.2.3 Leachate

Leachate is any liquid that has come into contact with waste or waste processing areas. It is generated through the management of waste delivered to the site.

Putrescible waste handled at the BTT can generate leachate that, if not contained, has the potential to reach surface or groundwater and cause pollution.

Predicted impacts from leachate include:

- Accidental release of leachate from the leachate storage tank;
- Release of leachate from putrescible waste to stormwater that may then cause pollution of surface water.



Page: Page 18 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016

#### Soil, Water and Leachate Management

## SECTION 4 SOIL, WATER AND LEACHATE MANAGEMENT MEASURES

#### 4.1 Erosion and Sediment Control Plan

Potential soil impacts have been mitigated at the BTT through the construction of the BTT hardstand, buildings, roadway, site drainage and detention facilities or rail corridor, across most of the site.

Consequently there is no residual risk of soil erosion on site during the operation stage.

Ongoing regular inspection and maintenance of the hardstand area will form part of the checks for the BTT site.

Should any further excavations works be required at the facility that may encounter contaminated soil and groundwater, the Long Term Environmental Management Plan (Appendix E) would be triggered.

#### 4.2 Stormwater Management Plan

The drainage strategy for the BTT facility is generally to maintain the existing flow paths on the BTT, while providing for adequate on site detention (OSD) to meet the City of Botany Bay Council's *Stormwater Management Technical Guidelines*.

The BTT stormwater management system has been designed in consultation with the City of Botany Bay Council to achieve Council's requirement of 20% AEP 'natural condition' detention.

The system provides adequate on site detention capacity to offset the calculated flood storage volume of 810 m<sup>3</sup>, as infiltration systems are not permitted on site due to the high groundwater level.

The system has the capacity to manage runoff generated under a range of conditions, and to be effective in the capture of sediment and gross pollutants. It also has capability for management of oils/greases and fuel spills.

This system provides for the management of stormwater separate from the management of leachate, while also controlling water quality.

The stormwater management system includes the following key elements:

- Minor (in-ground) drainage system designed to convey the 1 in 20 year ARI storm event
- Major (overland) drainage system designed to safely convey the 1 in 100 year ARI storm event via dedicated overland flow paths to the point of discharge for the site on McPherson Street
- Stormwater quantity managed by a number of storage locations through the site
- Rainwater collected and re-used for washdown, toilet flushing and irrigation to meet City of Botany Bay Council requirements

Refer to Appendix A for a set of drawings showing the details of the stormwater management system (CO12589.00-C40 to CO12589.00-C48).



#### 4.2.1 <u>Treatment</u>

PLAN

Potential stormwater quality impacts have been mitigated by incorporating treatment solutions into the stormwater management system based the approach in the NSW EPA document *Managing Urban Stormwater: Treatment Techniques.* This approach ensures that the design incorporates the principles of Water Sensitive Urban Design (WSUD) and to target pollutants that are present in the stormwater so as to minimise the adverse impact these pollutants could have on receiving waters and to also meet the requirements specified by the City of Botany Bay Council.

WSUD measures have been incorporated into the OSD areas to attenuate stormwater flows and treat run-off for gross pollutants, suspended solids and nutrients before entering the drainage system.

Oil and grease interceptors are installed in all new drainage pits to ensure that 95% of oils and grease are captured before entering the off-site drainage system.

Components of the treatment solution include:

- Primary treatment to parking and hardstand areas via a Humeceptor hydrodynamic separation system
- Treatment of the rail siding area via a second Humeceptor hydrodynamic separation system
- Tertiary treatment of a portion of roof via rainwater reuse tanks.

The remainder of the roof water catchment, which is generally considered to contain small levels of pollution, bypasses the main treatment measures. Removal of gross pollutants is via a trash screen within the OSD system.

#### 4.2.2 On Site Detention

Due to the high groundwater level at the BTT, On Site Detention (OSD) devices are required to offset the existing flood storage at the site

Two OSD components have been provided on the Keith Engineering land and one OSD permanent sediment basins has been provided on the Asciano land. The location of all OSD system components are shown on the Stormwater Drainage Plan (CO12589.00-C41 (Refer to Appendix A).

Stormwater quantity will be managed by a number of storage locations. The storage locations can be described as follows:

- OSD 1 (207m<sup>3</sup>): In-ground tank located on the south-east corner of the building managing roof water catchment (Refer to Drawing CO12589.00-C41 and CO12589.00-C47, Appendix A);
- OSD 2 (158m<sup>3</sup>): In-ground tank located to the south-west of the building under the car park, managing car park and a portion of the fire access road catchments (Refer to Drawing CO12589.00-C41 and CO12589.00-C47, Appendix C);
- OSD 3 (635 m<sup>3</sup>): above ground storage open based basin in the northern extent between the concrete hardstand and the rail sidings area. This basin is open based allowing for infiltration into the Botany aquifer (Refer to Drawing CO12589.00-C48, Appendix ).

Consequently, the BTT includes the provision of approximately 1,000 m<sup>3</sup> of OSD sufficient to offset the calculated flood storage volume of 810 m<sup>3</sup> as required.



#### Page: Page 20 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016

#### Soil, Water and Leachate Management

#### 4.2.3 Operation of the BTT Stormwater System

Rainfall that collects to the west of the rail sidings flows into a stormwater pipe. This conveys the water to the northern portion of the BTT and into OSD3. This then transfers the water into a gross pollutant trap (GPT) for discharge via a pipe located on the west of Keith Engineering in a southerly direction, towards McPherson Street.

Bunding along the western boundary of the BTT ensures that no flows from the BTT enter the Botany Goods Line. In addition, bunding or kerbing installed along the western boundary of the site prevents stormwater from entering ARTC's land.

OSD 3 is located at the northern portion of the BTT. It captures overland flow run-off. The layout of the system ensures that on-site run-off can be stored for a period of time while smaller flows are released into the drainage infrastructure before connecting into the Council drain in McPherson Street.

#### 4.2.4 Rainwater Harvesting

Rainwater harvesting has been incorporated into the site, with the collection of stormwater from roof areas for re-use in non-potable applications.

This water is used on site for toilet flushing, washing down area, such as cleaning of the compactor pit, and irrigation. These uses all contribute to minimising the potable water demand on site.

The rainwater harvesting system consists of an in-line tank, which is located beneath the transfer terminal building. Water is pumped from the tank for distribution throughout the site in a dedicated non-potable water reticulation system.

The system enables rainwater to pass through the tank if it is full and continue to be discharged via gravity into the stormwater drainage system.

The tank is connected to the mains water supply to allow for replenishment during extended dry periods. A float switch will turn a pump on when the tank capacity reaches 10% and will switch off once the capacity reaches 20%. All pumps associated with the rainwater harvesting system have been installed in accordance with the City of Botany Bay Council requirements.

#### 4.3 Leachate Management Plan

The leachate management system for the BTT is independent of the stormwater system for the site, ensuring that separation between rainfall run-off and leachate is maintained at all times. The compactor areas are fully covered to limit the generation of leachate.

The BTT leachate management strategy for the BTT focuses on the operation of bunded areas within the terminal building where waste is transferred from trucks to the shipping containers for transport to the Woodlawn site.

Two leachate tanks, each of 32kL capacity, have been installed below the transfer terminal building. These will capture all leachate from the tipping floor, around the compactors and wash-down water. The location of the leachate tanks and associated infrastructure is provided in the Hydraulic Services Warehouse Plan H-200 (refer to Appendix A).

All excess leachate from the operations will be disposed of in accordance with regulatory requirements. Leachate will be pumped into a dedicated ISO tanker that will be loaded and transported to Woodlawn or be pumped and transported from site and disposed in an appropriately licenced facility.

#### PLAN



Page 21 of 36 PLA-NSW-XXX-XXX-1 Document: 23.06.2016

#### Soil, Water and Leachate Management

Page:

Date:

#### 4.4 Other control measures

The design of the BTT facility includes a self-bunded diesel fuel storage facility to mitigate risks associated with this facility and its use. All refuelling takes place within this area. The fuel tank is located to the north of the compaction area, as shown in the Architectural Plan A200 (Refer to Appendix A).

The design of the BTT also incorporates a dedicated area and a method for managing hot loads. This specification is shown in the Specifications for Management of Hot Loads (Refer to Appendix C)

Printed documents are uncontrolled versions. Check printed copies against the current electronic version for validity.



Page:Page 22 of 36Document:PLA-NSW-XXX-XXX-1Date:23.06.2016

Soil, Water and Leachate Management

# SECTION 5 SOIL, WATER AND LEACHATE MONITORING AND REPORTING

#### 5.1 Monitoring Program

Inspection, testing and monitoring will be undertaken at the BTT, in accordance with the site specific inspection and testing register. The outcomes of monitoring will be recorded in appropriate forms/checklists as detailed in Section 5.1.1 of the OEMP.

There will be ongoing and regular inspection and maintenance of the hardstand area on the BTT site to ensure that the integrity of the stand is intact and that capped soils beneath the stand are not at risk of disturbance.

Inspection and monitoring checklists for water quality management and infrastructure during the operational phase of the BTT will be held on Veolia's document management system. This will ensure that all monitoring activities can be used to minimise the potential impact of any emissions.

Baseline water monitoring data is provided in Appendix D.

#### 5.1.1 Stormwater Monitoring

The Facility Manager is responsible for monitoring the effectiveness of all environmental measures in place to manage stormwater quality and infrastructure on site. The Technical and Engineering team will undertake environmental compliance monitoring, if required.

No uncontrolled stormwater discharges off-site will be permitted unless the design capacity for the sediment basins is exceeded during intensive rainfall events.

Based on the EPL limits all controlled water releases off-site must meet the following stormwater runoff requirements prior to discharge as show in

Table 5.1.

Parameter	Unit of Measure	100 percentile limit	Frequency	
Biological Oxygen Demand	mg/L	10	As required, or following a rainfall	
Nitrogen (Ammonia)	mg/L	1	event after each 6	
Oil & Grease	mg/L	10	monthly maintenance check	
рН	рН	6 – 8.5		
Total Suspended Solids	mg/L	50		

 Table 5.1 Stormwater Runoff Discharge Requirements



Stormwater infrastructure is also monitored on a regular basis to ensure that each

component is properly operated and maintained. The frequency of inspections may vary depending on site specific attributes and rainfall patterns. Details of the stormwater maintenance schedule are provided in Appendix B. In addition to the nominated frequencies, inspections will also be undertaken following large storm events.

#### 5.1.2 Groundwater Monitoring

Previous groundwater monitoring shows that groundwater chemical results for the site are consistent with the expected regional background concentrations associated with the Orica plume as the site is located in zone 1 of the Botany Groundwater Management Zone. The Botany Bay aquifer and receiving environments are disturbed and highly modified in nature.

The validation report prepared by DLA Environmental for the remediation works undertaken during construction of the facility concluded that groundwater is not considered to represent a significant risk of exposure to receptors for the following reasons:

- The risk of the interaction between on-site receptors and the groundwater is greatly reduced under the non-sensitive commercial/industrial land use of the site
- Current and future access to groundwater at the site is limited due to the restriction placed on abstraction of groundwater for any use
- The site has been capped by the development, including raising site levels

Three groundwater monitoring wells have been installed at the site (refer to Appendix F). Monitoring of these wells is completed in accordance with the Table 5.2 below.

Monitoring Locations	Parameters	Unit	Frequency	Sampling Method
	EC	µS/cm	Six monthly	Grab sample
GW1,GW2 &	рН	рН		
GW3	Total Dissolved Solids, TDS	mg/L		
	Ammonia	mg/L		
	BOD	mg/L		
	Water Level	М		

 Table 5.2 Groundwater Monitoring Program

#### 5.1.3 Leachate Monitoring

Details of the leachate management system are provided in Section 4.3, including the transport and disposal of leachate off site for disposal at an appropriately licensed facility. Any testing or monitoring required by the disposal facility will be undertaken to ensure the leachate will meet the requirements of the disposal facility.

As a part of the weekly site inspection checklist, the leachate tank levels are monitored and the areas of the site where leachate is generated or stored are inspected.



Page:	Page 24 of 36
Document:	PLA-NSW-XXX-XXX-1
Date:	23.06.2016

Further, the containers are inspected to ensure seals are in good working order and that any full containers remain closed and intact. Any containers identified as potentially being compromised, will be cleaned & isolated for further inspection, and maintenance will be done as required.

#### 5.2 **Performance Reporting and Review**

Annual management reviews of the environmental performance of the BTT will assess the continuing suitability, adequacy and effectiveness of the on-site environmental management measures implemented. This review will include performance against the goals of the SWLMP.

Where performance reporting is required under the Consent Conditions or EPL, all relevant environmental monitoring data and information will be recorded and maintained on site. This will include, but not be limited to, the following:

- Sampling dates, times and name of sampler;
- Chain of Custody, analysis and results;
- Complaints received and corrective actions taken; and
- Copy of the EPL, development consent and other relevant approvals.

Veolia will use monitoring data to review and identify any exceedances against the adapted goals with the appropriate corrective actions applied as discussed below.

Details of compliance reporting requirements are provided in Section 5.1.2 of the OEMP.

#### 5.3 Exceedances and Corrective Actions

Details of exceedances and corrective action for any soil, water or leachate related incidents are provided as part of the response plan detailed in section 6 of the SWLMP.

#### 5.4 Publishing of Monitoring Data

Where required, Veolia publishes the results of any environmental monitoring required under the EPL on the following website:

http://www.veolia.com.au/sustainable-solutions/environmental-compliance/nswenvironmental-monitoring-data



Page:	Page 25 of 36
Document:	PLA-NSW-XXX-XXX-1
Date:	23.06.2016

### SECTION 6 SURFACE WATER, GROUNDWATER AND LEACHATE RESPONSE PLAN

In line with the regulatory requirements, a response plan has been prepared detailing the measures to be implemented in response to any surface or groundwater contamination that may be arise through operation of the BTT, as well as a protocol for the investigation, notification and mitigation of any exceedances of the respective trigger levels.

Table 6.1 below describes the actions to be taken in the event that there is an exceedance of the trigger levels for surface water listed in the monitoring program in Section 5.1.

Location	Parameter	Criteria/ Performance Measure/Trigger	Action	Responsibility
Surfacewater	As per the table 5.1	As per the table 5.1	Follow incident process Where applicable, report exceedance to DPE, City of Botany Bay Council and any other relevant government agency	Environmental representative/ Facility Manager/SHEQ
Groundwater	As per BTT Site analytes testing regime	Existing groundwater network performance against baseline	Review groundwater monitoring results; Identify exceedance, consider resampling and/or continue periodic monitoring to gauge any upward trends; Where applicable, report exceedance to DPE, City of Botany Bay	Environmental representative/ Facility Manager/SHEQ

#### **Table 6.1 Exceedence Trigger and Actions**



Page:	Page 26 of 36
Document:	PLA-NSW-XXX-XXX-1
Date:	23.06.2016

Soil, Water and Leachate Management

agency
--------

Handling of any soil, water and leachate related incidents will be managed in accordance with the process outlined in Section 4.4 of the OEMP. The Facility Manager, or their site nominee, will record and manage all incidents in accordance with Veolia's incident notification and reporting procedures.

Incidents will be managed in accordance with Veolia's Non Conformance Procedure (PRO-COL-000-137). Investigations will be undertaken in accordance with the NSW Incident Investigation Procedure (PRO-NSW-000-130) or on a case by case basis depending on the severity of the incident as described Section 5.1.1 of the OEMP.

At completion of any investigation, any corrective actions required will be recorded in the Vault and managed in accordance with the NSW Corrective Action Procedure (PRO-NSW-000-132) in a timely manner.


An Emergency Response Plan (ERP) has been developed for the BTT site and is appended to the OEMP. The ERP (refer Appendix D7), identifies the procedures to be followed in the event of an emergency and is to be used as the protocol in the event of an exceedance. The process for dealing with potential incidents and emergencies at the BTT is summarised in Figure 6.1.



Page:	Page 27 of 36
Document:	PLA-NSW-XXX-XXX-1
Date:	23.06.2016

#### **Emergency and Environmental Incident Response Flow-Chart**

This flowchart provides a basic guideline to emergency response. As such it cannot predict every emergency situation that could occur. Never place yourself or others at risk when following these procedures. Refer to your site Emergency Response Plan for further information.





#### PLAN




This process guides any response to surface water, groundwater or leachate contamination through such incidents as spills or discharges, which may include the use of absorbent material to contain the spill/discharge.

Spill kits are available onsite at all times and training in their use is provided to all BTT personnel.

Any fuel, lubricant, or hydraulic fluid spillages is contained through the design of site bunding, and any excess material is collected using absorbent material, with contaminated material disposed of to a licensed waste facility.

A typical spill response procedure to be followed by Veolia is summarised in Figure 6.2 below.





Page: Page 29 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016

#### **PLAN**

Soil, Water and Leachate Management

### SECTION 7 REFERENCES

- ANZECC, 2000, The Australian Water Quality Guidelines for Fresh and Marine Waters
- Landcom (2004), *Managing Urban Stormwater*, 4<sup>th</sup> Edition.
- City of Botany Bay Council, (2013), *Stormwater Management Technical Guidelines.*
- Costin Roe Consulting Pty Ltd, (2015), Civil Engineering Report.
- Hyder Consulting Pty Ltd, (2014), *Banksmeadow Transfer Terminal Response* to Submissions.
- Hyder Consulting Pty Ltd, (2014), Banksmeadow Transfer Terminal Environmental Impact Statement.
- NSW EPA (1997), Managing Urban Stormwater: Treatment Techniques.



Page: Page 30 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016 Soil, Water and Leachate Management

**APPENDICES** 




Page: Page 31 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016 Soil, Water and Leachate Management


#### PLAN

Soll, Water and Leachate Wa

#### Appendix A Site Plans


Stormwater Management System CO12589.00 C40 to CO12589.00 C48 Hydraulic Services Warehouse Plan H-200 (Leachate tanks) Architectural Plan A200 (Fuel tank)







	VEOLIA TERMINAL						CONSULT AUSTRALIA	Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 696 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731	Costin	
DESIGNED M.W.	DRAWN X.C.	DATE	CHECKED		SCALE AS SHOWN	CAD	REF: 12589.00-C48	email: mail@costinroe.com.au ©	Value in Eng	

ngineering and Management DRAWING Nº CO12589.00- C48








	LIA		<b>1INAL</b> ET, BANI	<sm< th=""><th>EADOW</th><th>CONSULT AUSTRALIA</th><th>Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 606 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731</th><th>CostinF</th></sm<>	EADOW	CONSULT AUSTRALIA	Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 606 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731	CostinF
DESIGNED M.W.	DRAWN X.C.	DATE	CHECKED		SCALE AS SHOWN	CAD REF: 12589.00-C47	email: mail@costinroe.com.au ©	Value in Eng


Ingineering and Management DRAWING No CO12589.00- C47



DESIGNED DRAWN DATE M.W. X.C.


	500mm 0 1 LL. SCALE 1:50 AT A	2 3 4 5m 0 SIZE SHEET
ТΕ	200mm 0 5 لساسا SCALE 1:20 AT A	00 1000 1500 2000mm   0 SIZE SHEET
Roe	Consulting	DRAWING TITLE STORMWATER DRAINAGE DETAILS – SHEET 2


ngineering and Management	<sup>drawing n</sup> <sup>o</sup> CO12589.00− C46	



DATE ISSUE AMENDMENTS

AMENDMENTS





# SINGLE GRATED GULLY PIT - SGGP


DATE ISSUE

DESIGNED DRAWN DATE M.W. X.C. CHECKED SIZE SCALE CAD REF: A0 AS SHOWN 12589.00-45 email: mail@costinroe.com.au ©

Value in Engi

— FILL AS SPECIFIED — 19mm GRAVEL 90% RET						
ON 9.5 SEIVE — 90 DIA SLOOTED PIPE V GEOTEXTILE STOCKING	√ITH					
TRENCH BOTTOM						
AIN						
						$\land$
			_			
	<u> </u>	<b>†</b>	FILL AS SPE		EXCAVATED	
		300	MATERIAL C LAYERS TO	90% STD DE	NSITY	
D.D.R)	<u> </u>	0.30D	_ 100 BEDDING	I COMPACTE	ED TO 60% S. D TO 60% D.I	
			— I <sub>c</sub> = 150mm F REFER TO		ES ≤900Ø. OR PIPE SIZ	ZES >900Ø.
<u>TYPE H1 SUPF</u> CONCRETE PII						
LANDSCAPED						
] TRENCH iREATER						
- 45° ELBOW						
PVC DOWNP CONNECTION 225Ø uPVC N	LINE					
O UPCV PIPE S SHALL BE USED TO EQUIRED TO UPVC PIPES .						
DLVENT WELDED JOINTS. E BEYOND THE INNER PE.						
ION DETAILS						
	200mm	0	500	1000	1500	2000mm

SATE SCALE 1:20 /	AT AO SIZE SHEET
oe Consulting	DRAWING TITLE STORMWATER DRAINAGE DETAILS – SHEET 1
ineering and Management	DRAWING Nº CO12589.00-45



REVISED AS CLOUDED	11.02.16	E			
LONGSECTIONS REVISED	26.10.15	D			
ISSUED FOR CONSTRUCTION CERTIFICATE	12.06.15	C			
ALL LONGSECTIONS REVISED	01.06.15	В			
ISSUED FOR INFORMATION	22.05.15	А			
AMENDMENTS	DATE	ISSUE	AMENDMENTS	DATE	E ISSUE

	Ονεοια
AMENDMENTS DATE ISSUE	





# FOR CONSTRUCTION CERTIFICATE


PROJECT VEOLIA TERMINAL MCPHERSON STREET, BANKSMEADOW

DESIGNEDDRAWNDATECHECKEDSIZESCALECADREF:M.W.X.C.13.05.15A0ASSHOWN12589.00-C44

CONSULT AUSTRALIA CONSULT AUSTRALIA D REF: 12589.00-C44 Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 696 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731 email: mail@costinroe.com.au ©









AMENDMENTS


						-
REVISED AS CLOUDED	11.02.16	F				Γ
REVISED AS CLOUDED FOR OSD 3 INLET PIPES	07.12.15	E				
LONGSECTIONS UPDATED	26.10.15	D				
ISSUED FOR CONSTRUCTION CERTIFICATE	12.06.15	C				
ALL LONGSECTIONS REVISED	01.06.15	В				Γ
ISSUED FOR INFORMATION	22.05.15	А				ſ
AMENDMENTS	DATE	ISSUE	AMENDMENTS	DATE	ISSUE	Γ
						-




1:100 VERTICAL
















FOR CONSTRUCTION CERTIFICATE VEOLIA TERMINAL

ONSULT AUSTRALIA McPHERSON STREET, BANKSMEADOW DESIGNED DRAWN DATE M.W. X.C. CHECKED SIZE SCALE CAD REF: A0 AS SHOWN 12589.00-C43

Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 696 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731 email: mail@costinroe.com.au ©







DESIGNED DRAWN DATE M.W. X.C.

CHE

CKED SIZE SCALE A0 AS SHOV







Value ir	
ר En	

Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 666 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731 email: mail@costinroe.com.au ©

VEOLIA TERMINAL MCPHERSON STREET, BANKSMEADOW NSULT AUSTRALIA

ד ק ק 

SHEET 2

 $\mathcal{O}$  ${\mathbb Z}$  $\square$ 

PIT B01 - RETAINING WALL < S S > er. < SS > - 8 ACO POWERDRAIN S300K (CLASS G) OR APPROVED EQUIVALENT AT BASE OF WEIGHBRIDGE RAMP WITH 600SQ PIT WITH \$225 OUTLET. < SS > SS ≤ (6.) (x) (x) ~ss~  $\overline{\mathbb{J}}$ Ţ < SS < < S \$ <SS> 01.0) SZ. X) ~X <SS> \$225 @ 1% < S S > TRACK DRAINAGE PIT-4 REFER TO RHOMBERG DRAWING 15002-SW-001 FOR PIT LOCATION & 15002-DR-001 FOR PIT DETAILS. < S S > 7.90 °6:-X) 244 ACO POWERDRAIN S300K (CLASS G) OR APPROVED EQUIVALENT. <SS> SWN s s v -0---5₩> 0225 @ 1% < SS > 9-. ) - x €€. \ × ss v 7.10 SW> SS > < 22 XT.X TX Ĩ**∭───┿**╎≯/Ī■

4<del>000</del> S

RY M V

 $\Box$ 

V C T

9

RETA

드

WALL

<u>TOP OF CABLE TILES:</u>-132Kv RL 5.632 <u>STORMWATER PIPE</u> Ø450 IL 5.950 (300mm CLEARANCE)

L

Z

v ~ ~

6


 $\bigcirc$ 


5

9

8.00 -7.90 V V  $\mathcal{M}$ V Ν V  $\mathbf{V}$ 1.70 ≤ 50 525 AW B 9

	Value in Engineering and Mana				
		STORMWA REFER TO DRAV REFER TO DRAV 2m 0 2m 0 Lunum L L L L SCALE 1:25		LECELND:         LEVELS DATUM IS AHD.         EXISTING SITE LEVELS AND INFORMATION PROVIDED BY DATED 31 JAN 2013.         Image: Structure of the struct	
L012289.00-C42	STORMWATER DRAINAGE PLAN SHEET 2 ACCESS ROAD	NING C	VEGETATION	3. SGEP, SINGLE GRATED GULLY PIT SJP, SEALED JUNCTION PIT KIP, KERB INLET PIT TRACK DRAINAGE PIT (BY RHOMBERG) DBAINAGE LINE TRACK DRAINAGE LINE (BY RHOMBERG) SUBSOL LINE IN-GROUND ROOFWATER LINE SYPHONIC ROOFWAT	





DATE ISSUE

AMENDMENTS


RAIL SIDING LEVELS REVISED & TRACK DRAINAGE & SERVICES ADDED	31.07.15	F			
REVISED FOR UPDATED ARCHI LAYOUT	17.07.15	E			
ISSUED FOR CONSTRUCTION CERTIFICATE	12.06.15	D			
STORMWATER REVISED AS CLOUDED	01.06.15	C	REVISED AS CLOUDED	11.02.16	I
STORMWATER REVISED	22.05.15	В	REVISED AS CLOUDED FOR OSD3 INLET PIPES & GAS MAIN ENCAS	SEMENT 07.12.15	Н
ISSUED FOR INFORMATION	15.05.15	А	REVISED AS CLOUDED	26.10.15	G
AMENDMENTS	DATE	ISSUE	AMENDMENTS	DATE	ISSUE

OLIA TERMINAL PHERSON STREET, BANKSMEADOW	CONSULT AUSTRALIA	Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 606 446 Level 1, 8 Windmill Street	

Value in Engin

Roe	Consulting	

	SHEET 1 PROPOSED SITE
neering and Management	DRAWING № CO12589.00–C41



### STORMWATER DRAINAGE NOTES:

- 1. ALL STORMWATER WORKS TO BE COMPLETED IN ACCORDANCE WITH AUSTRALIAN STANDARD AS3500.3:2003 PLUMBING AND DRAINAGE, PART 3: STORMWATER DRAINAGE.
- THE MINOR (PIPED) SYSTEM HAS BEEN DESIGNED FOR THE 1 IN 20 YEAR ARI STORM EVENT AND THE MAJOR (OVERLAND) SYSTEM HAS BEEN DESIGNED FOR THE 1 IN 100 YEAR ARI STORM EVENT.
- 3. ALL FINISHED PAVEMENT LEVELS SHALL BE AS INDICATED ON FINISHED LEVELS PLANS (51 & (52.
- 4. PIT SIZES SHALL BE AS INDICATED IN THE SCHEDULE WHILE PIPE SIZES AND DETAILS ARE PROVIDED ON PLAN.
- 5. EXISTING STORMWATER PIT LOCATIONS AND INVERT LEVELS TO BE
- CONFIRMED BY SURVEY PRIOR TO COMMENCING WORKS ON SITE.
- ALL STORMWATER PIPES Ø375 OR GREATER SHALL BE CLASS 2 REINFORCED CONCRETE WITH RUBBER RING JOINTS UNLESS NOTED OTHERWISE.
   ALL PIPES UP TO AND INCLUDING Ø300 TO BE uPVC GRADE SN8 UNO.
- 8. PIPE CLASS NOMINATED ARE FOR IN-SERVICE LOADING CONDITIONS ONLY. CONTRACTOR IS TO MAKE ANY NECESSARY ADJUSTMENTS REQUIRED FOR CONSTRUCTION CONDITIONS.
- 9. ALL CONCRETE PITS GREATER THAN 1000mm DEEP SHALL BE REINFORCED USING N12-200 EACH WAY CENTERED IN WALL AND BASE. LAP MINIMUM 300mm WHERE REQUIRED. ALL CONCRETE FOR PITS SHALL BE F'c 25 MPA. PRECAST PITS MAY BE USED WITH THE APPROVAL OF THE ENGINEER.
- IN ADDITION TO ITEM 6 ABOVE, ALL CONCRETE PITS GREATER THAN 3000mm DEEP SHALL HAVE WALLS AND BASE THICKNESS INCREASED TO 200mm.
   PIPES SHALL BE LAID AS PER PIPE LAYING DETAILS DADTICLU AD CADE
- 11. PIPES SHALL BE LAID AS PER PIPE LAYING DETAILS. PARTICULAR CARE SHALL BE TAKEN TO ENSURE THAT THE PIPE IS FULLY AND EVENLY SUPPORTED. RAM AND PACK FILLING AROUND AND UNDER BACK OF PIPES AND PIPE FAUCETS, WITH NARROW EDGED RAMMERS OR OTHER SUITABLE TAMPING DETAILS.
- 12. WHERE PIPE LINES ENTER PITS, PROVIDE 2m LENGTH OF STOCKING WRAPPED SLOTTED Ø100 uPVC TO EACH SIDE OF PIPE.
   13. ALL SUBSOL DEALWARE STUDIES STUDIES FOR THE STOCKING WRAPPED FOR THE SUBSOL OF PIPE.
- 13. ALL SUBSOIL DRAINAGE LINES SHALL BE Ø100 SLOTTED uPVC WITH APPROVED FILTER WRAP LAID IN 300mm WIDE GRANULAR FILTER UNLESS NOTED OTHERWISE. LAY SUBSOIL LINES TO MATCH FALLS OF LAND AND/OR
  1 IN 200 MINIMUM. PROVIDE CAPPED CLEANING EYE (RODDING POINT) AT UPSTREAM END OF LINE AND AT 30m MAX. CTS. PROVIDE SUBSOIL LINES TO ALL PAVEMENT/ LANDSCAPED INTERFACES, TO REAR OF RETAINING WALLS (AS NOMINATED BY STRUCTURAL ENGINEER) AND AS SHOWN ON PLAN.
  14 ALL PIPE GRADES 1 IN 100 MINIMUM LINO
- ALL PIPE GRADES 1 IN 100 MINIMUM UNO.
   PROVIDE STEP IRONS IN PITS DEEPER THAN 1000mm.
- 16. MIN. 600 COVER TO PIPE OBVERT BENEATH ROADS & MIN. 400 COVER
- BENEATH LANDSCAPED AND PEDESTRIAN AREAS. 17. PIT COVERS IN TRAFFICABLE PAVEMENT SHALL BE CLASS D 'HEAVY DUTY',
- THOSE LOCATED IN NON-TRAFFICABLE AREAS SHALL BE CLASS B 'MEDIUM DUTY' U.N.O.
- PROVIDE CLEANING EYES (RODDING POINTS) TO PIPES AT ALL CORNERS AND T-JUNCTIONS WHERE NO PITS ARE PRESENT.
   DOWN PIPES (DP) TO BE AS PER HYDRAULIC ENGINEERS DETAILS WITH
- CONNECTOR TO MATCH DP SIZE U.N.O. ON PLAN. PROVIDE CLEANING EYE AT GROUND LEVEL. 20. PIPE LENGTHS NOMINATED ON PLAN OR LONGSECTIONS ARE MEASURED
- FIEL LENGTHS NOMINATED ON PLAN OR LUNGSECTIONS ARE MEASURED FROM CENTER OF PITS TO THE NEAREST 0.5m AND DO NOT REPRESENT ACTUAL LENGTH. THE CONTRACTOR IS TO ALLOW FOR THIS.

# FOR CONSTRUCTION CERTIFICATE

VEOLIA TERMINAL MCPHERSON STREET, BANKSMEADOW

McPHERSON STREET, BANKSMEADOW

Costin Roe Consulting Pty Ltd. Consulting Engineers ACN 003 696 446 Level 1, 8 Windmill Street Walsh Bay, Sydney NSW 2000 Tel: (02) 9251-7699 Fax: (02) 9241-3731 email: mail@costinroe.com.au ©

Costin

Value in Eng

ARI (YEARS)		ADOPTED PSD (L/s) BASED ON 5YR 15MINS STORM	CRITICAL STORM DURATION	UN-ATTENUATED POST- DEVELOPMENT PEAK FLOWS (L/s)	ATTENUATED POST- DEVELOPMENT PEAK FLOWS (L/s)	OSD STORAGE (m³)
5	948	741	2 HOUR	1180	550	444
20	1320	741	2 HOUR	1540	641	711
100	1710	741	2 HOUR	1930	737	1065

## DETAILED SITE DISCHARGE SUMMARY

ALL FLOWS SHOWN HAVE BEEN CALCULATED USING 'DRAINS' SOFTWARE

IT No.	GRATE RL	DEPTH	TYPE	SIZE	COMMENT
PIT A01	7.10	1100	SGGP	900x900	
PIT A02	6.50	900	SGGP	900x900	
PIT A03	6.97	1470	SGGP	900x900	
PIT A04	6.30	970	SGGP	900x900	
PIT A05	6.30	1090	SGGP	900x900	
PIT A06	6.30	1210	SGGP	900x900	
PIT A07	6.05	1120	SGGP	900x900	
PIT A08	5.40	1120	SGGP	900x900	
PIT A09	4.80	890	SGGP	900x900	
PIT A10	4.88	1020	SGGP	900x900	
PIT A11	4.90	830	SGGP	900x900	
PIT A12	4.90	1050	SGGP	900x900	
PIT A13	4.95	1280	SGGP	900x900	
PIT A14	4.95	1540	SJP	900x900	
PIT A15	6.22	1520	SJP	900x900	
PIT A16	6.02	1380	SJP	900x900	
PIT A17	5.49	960	SJP	900x900	
PIT A18	4.85	1500	SJP	900x900	
PIT A19	4.75	1460	SJP	900x900	
IT SCH	EDULE -	NETWO	<u>DRK 'B'</u>		
PIT No.	GRATE RL	DEPTH	TYPE	SIZE	COMMENT
PIT B01	7.90	1200	SGGP	1200x1200	
PIT B02	7.20	1200	SGGP	900x900	
PIT B03	7.48	1580	SGGP	900x900	
	-			1	

### <u> PIT SCHEDULE – NETWORK 'C'</u>


PIT No.	GRATE RL	DEPTH	TYPE	SIZE	COMMENT
PIT C 01	5.00	1000	SGGP	1200x1200	
PIT C 02	6.00	4100	SGGP	1200×1200	
PIT C 03	6.16	2010	SJP	1500x1200	
PIT C 04	4.95	1290	SJP	1200×1200	
PIT C 05	4.95	1320	SJP	1200×1200	
PIT C 06	4.90	1640	SJP	2100x900	


 PIT B 05
 6.55
 1120
 SGGP
 1200x1200
 CLASS 'G' LID

PIT B 06 6.20 1000 SGGP 1200×1200 CLASS 'G' LID

5m 0 10 20 30 40 50m L....L. I:500 AT A0 SIZE SHEET

Roe Consulting	DRAWING TITLE STORMWATER CATCHMENT PLAN NOTES & PIT SCHEDULE
ngineering and Management	DRAWING No CO12589.00-C40 F







Page:Page 32 of 36Document:PLA-NSW-XXX-XXX-1Date:23.06.2016

PLAN

Soil, Water and Leachate Management

Appendix B Stormwater Infrastructure Maintenance Schedule

### STORMWATER INFRASTRUCTURE MAINTENANCE SCHEDULE

Stormwater infrastructure is monitored on a regular basis to ensure that each component is properly operated and maintained. The following table provides a list of key maintenance actions, the frequency of inspections, responsibility and procedure. These frequencies may vary depending on site specific attributes and rainfall patterns. In addition to the nominated frequencies, inspections will also be undertaken following large storm events.

MAINTENANCE ACTION	FREQUENCY	RESPONSIBILITY	PROCEDURE
SWALES/ LANDSCAL	PED AREAS		
Check density of vegetation and ensure minimum height of 150mm is maintained. Check for any evidence of weed infestation	Six monthly	Maintenance Contractor	Replant and/or fertilise, weed and water in accordance with landscape consultant specifications
Inspect swale for excessive litter and sediment build up	Six monthly	Maintenance Contractor	Remove sediment and litter and dispose in accordance with local authorities' requirements.
Check for any evidence of channelisation and erosion	Six monthly/ After Major Storm	Maintenance Contractor	Reinstate eroded areas so that original, designed swale profile is maintained
Weed Infestation	Three Monthly	Maintenance Contractor	Remove any weed infestation ensuring all root ball of weed is removed. Replace with vegetation where required.
Inspect swale surface for erosion	Six Monthly	Maintenance Contractor	Replace top soil in eroded area and cover and secure with biodegradable fabric.

MAINTENANCE ACTION	FREQUENCY	RESPONSIBILITY	PROCEDURE				
			Cut hole in fabric and revegetate.				
RAINWATER TANK							
Check for any clogging and blockage of the first flush device	Monthly	Maintenance Contractor	First flush device to be cleaned out				
Check for any clogging and blockage of the tank inlet - leaf/litter screen	and blockage Contractor ik inlet -		Leaves and debris to be removed from the inlet leaf/litter screen				
Check the level of sediment within the tank		Maintenance Contractor	Sediment and debris to be removed from rainwater tank floor if sediment level is greater than the maximum allowable depth as specified by the hydraulic consultant				
INLET & JUNCTION	PITS						
inside Pit Six Monthly		Maintenance Contractor	Remove grate and inspect internal walls and base, repair where required. Remove any collected sediment, debris, litter.				
Outside of Pit	Four Monthly/ After Major Storm	Maintenance Contractor	Clean grate of collected sediment, debris, litter and vegetation.				
STORMWATER SYST	ГЕМ	•					
General Inspection of complete stormwater drainage system	Bi-annually	Maintenance Contractor	Inspect all drainage structures noting any dilapidation in structures and carry out required repairs.				
HUMECEPTOR							
Refer ManufacturersReferOperation andManufacturersMaintenance ManuelOperation andfor maintenanceMaintenancerequirements.Manuel		Maintenance Contractor	Refer Manufacturers Operation and Maintenance Manuel				
OSD TANK/ BASINS							
Inspect and remove any blockage from	Six Monthly	Maintenance Contractor/ Owner	Remove grate and screen to inspect orifice.				

MAINTENANCE ACTION	FREQUENCY	RESPONSIBILITY	PROCEDURE		
orifice					
Inspect trash screen and clean	Six Monthly	Maintenance Contractor/ Owner	Remove grate and screen if required to clean it.		
Inspect flap valve and remove any blockage.	Six Monthly	Maintenance Contractor/ Owner	Remove grate. Ensure flap valve moves freely and remove any blockages or debris.		
Inspect pit sump for damage or blockage.	Six Monthly	Maintenance Contractor/ Owner	Remove grate & screen. Remove sediment/ sludge build up and check orifice and flap valve is clear.		
Inspect storage areas and remove debris/ mulch/ litter etc likely to block screens/ grates.	Six Monthly	Maintenance Contractor/ Owner	Remove debris and floatable materials.		
Check attachment of orifice plate and screen to wall of pit	Annually	Maintenance Contractor	Remove grate and screen. Ensure plate or screen mounted securely, tighten fixings if required. Seal gaps if required.		
Check orifice diameter is correct and retains sharp edge.	Five yearly	Maintenance Contractor	Compare diameter to design (see Work-as- Executed) and ensure edge is not pitted or damaged.		
Check screen for corrosion	Annually	Maintenance Contractor	Remove grate and screen and examine for rust or corrosion, especially at corners or welds.		
Inspect overflow weir and remove any blockage	Six monthly	Maintenance Contractor/ Owner	Ensure weir is free of blockage.		
Inspect walls for cracks or spalling	Annually	Maintenance Contractor	Remove grate to inspect internal walls, repair as necessary.		
Check step irons	Annually	Maintenance Contractor	Ensure fixings are secure and irons are free from corrosion.		



Page:Page 33 of 36Document:PLA-NSW-XXX-XXX-1Date:23.06.2016

PLAN

Soil, Water and Leachate Management

Appendix C Hot Load Management Specification



### NSW Banksmeadow Transfer Terminal Specifications for Hot Load Area & Equipment

#### **Specifications**

In the event that a waste transporting vehicle arrives to Banksmeadow carrying waste that is identified as smoldering (i.e hot load) it will be managed in a dedicated external area. The area will be located on the south-western corner on the entrance to the site, adjacent to the inbound access road as waste vehicles approach the incoming weighbridge. The area will be a clearly defined as emergency only parking area.

The hot load area is basically the same dimensions of a rigid truck and it is located in proximity to a fire hydrant which will be used in the event that a hot load is identified. The total estimated flow needs to be 1.0L per second. If any waste is dumped in the hot load area, the waste will be saturated with water.

Once the incident has been controlled, the majority of the waste will be collected by a front end loader and the remainder of the cleaning will be undertaken by a road sweeper and a skid steer.

The water that is utilised during the hot load incident and gets in contact with the smoldering waste will be classified as fire water. The majority of the water utilised will be absorbed by the waste based on the absorption capacity of putrescible waste. Putrescible waste has a moisture content of 20% and a saturation point of 50%, therefore there is 30% capacity for the fire water to be absorbed before we see any run-off.

With the existing flows of 1.0L per second and 6,000L to saturate the waste, it is very unlikely that a hot load would continue to be dealt with in 1hr 40min to reach saturation point.

However, in the event that there is excess run-off of fire water, it will drain towards pit B01. The pit will have drain protections installed as soon as the site is aware that there is a hot load event taking place. In addition to this protection, the road sweeper will be used to intercept any fire water and litter that may try to enter pit B01.

In the event that the closure of pit B01 is missed, the excess fire water will run into the site internal stormwater management system, specifically OSD 3. If any waste is identified in OSD 3, it will be accessed, cleaned & removed.

The discharge of OSD3 goes straight into a gross pollutant trap (GPT). The GPT will intercept any pollutant that would have made it to the stormwater drain. The GPT will be scheduled for cleaning as necessary. This process follows the "Guidelines for Contaminated Water retention and Treatment systems" of NSW.

#### Dimensions

Surface area at least 3m (W) x 12.5m (L) Total width of truck is 2.47m Same area as a temporary truck parking space

### Construction

Materials for floor same as road access area (concrete)

### NSW Banksmeadow Transfer Terminal Specifications for Hot Load Area & Equipment

Surface area must follow the same slope as the rest of the site for managing stormwater.

#### **Pipework & Hoses Specification**

Suitable to achieve 1.0L/s flow at the fire hydrant discharge point Suitable to resist heat (i.e. no plastic but stainless steel)

#### **Drain Specification**

Suitable to deal with leachate and fire water (i.e. 316 stainless steel) Size of drain pipe as per pit B01 1x drain on pit B01. Ease of access for maintenance and cleaning (i.e. at least 300mm SS drain)

#### **Calculations on capacity**

7 tonnes maximum payload per waste disposal truck
0.35 t/m<sup>3</sup> density of the waste once tipped
20m<sup>3</sup> of volume from the waste
20% moisture content of putrescible waste
50% Worst case saturation capacity for putrescible waste
10m<sup>3</sup> Maximum volume of water that would saturate the hot load
10,000L Maximum amount of moisture content before saturation of the putrescible waste
4,000L is 20% of the existing moisture content on the waste
6,000L is 30% absorption capacity for the putrescible waste before saturation

### **Calculations on flow**

1.0L/s total flow at the discharge points

60L per minute over the hot load

1hr 40mins time before saturation of the hot load waste at 50% saturation point

#### **Supporting Documentation**

- CO12589.00-C41-E Stormwater Drainage Plan Sheet 1
- CO12589.00-C42-E Stormwater Drainage Plan Sheet 2
- H-100[07] HYDRAULIC SERVICES SITE PLAN



Page: Page 34 of 36 Document: PLA-NSW-XXX-XX-1 Date: 23.06.2016

PLAN

Soil, Water and Leachate Management

Appendix D Baseline Water Data



Tuesday, 8 March 2016

DL3541\_S004265

Danny Germanos AWJ Civil Pty Ltd 155 Newton Rd Wetherill Park, NSW 2154

Danny@awj.com.au

Dear Sir,

#### Re: Groundwater Discharge to Stormwater Suitability – 34-36 McPherson Street, Banksmeadow NSW 2019.

DLA Environmental Services (DLA) was requested by AWJ Civil on the behalf of LIPMAN Pty Ltd to prepare a letter documenting the monitoring outcomes of groundwater dewatering works during discharge to stormwater at the property identified as 36 McPherson Street, Banksmeadow, NSW 2019.

Groundwater dewatering is an integral part of the planned construction program for the Site. The potential need to discharge on a daily basis is to allow Site excavations to proceed in a safe and efficient manner. As such, a responsible strategy for safeguarding environmental concerns and managing all potential risks associated with the dewatering exercise was implemented in the report titled: *Groundwater Dewatering Management Plan – 34-36 McPherson Street, 14 Beauchamp Road, Banksmeadow, NSW 2019* (DLA, 2015, ref: DL3541\_S003091\_R2). Permission to extract groundwater at the Site during excavation works has been provided by NSW Department of Primary Industries (DPI) Water.

DLA attended the Site on the 23<sup>rd</sup> February 2016 to undertake sample collection during dewatering activities. The water samples were collected from the discharge point currently in use at the Site, located on 34-36 McPherson Street directly adjacent the Site. The Site is not subject to consistent ongoing dewatering and only dewaters during selective civils work, thus giving rise to the irregular frequency of the sampling events.

#### Sydney

Melbourne

Brisbane

Adelaide

Newcastle

DLA Environmental Services Unit 3/38 Leighton Place Hornsby NSW 2077 (ASX: PEH) ABN: 80 601 661 634 sydney@dlaenvironmental.com.au Ph: +61 2 9476 1765

Perth

The results are as follows:

	Trigger	Action	23 <sup>rd</sup> March
Parameters	Levels	Criteria	2016
рН		<6.5 - >8.5^	7.2
Suspended Solids (TSS)	Visually turbid	50mg/L	nd
EC	750µs/cm	1000µs/cm	1800
Hydrocarbons			
Benzene	475µg/L	712.5µg/L	nd
Ethylbenzene	40µg/L*	60µg/L	nd
Toluene	55µg/L*	82.5µg/L	nd
p-Xylene	100µg/L	150µg/L	nd
o-Xylene	175µg/L	262.5µg/L	nd
TRH	300µg/L**	450µg/L	13
Metals			
Arsenic	12µg/L	18µg/L	3
Cadmium	0.35μg/L 0.53μg/L		nd
Chromium (III)***	13.5µg/L	20.3µg/L	2
Copper	0.7µg/L	1.1µg/L	nd
Lead	2.2µg/L	3.3µg/L	nd
Mercury	0.5µg/L	0.75µg/L	0.18
Nickel	5.5µg/L	8.3µg/L	2
Zinc****	7.5g/L	11.25µg/L	20
Chlorinated Compounds			
Chloroform*	30 µg/L		2
1,1 dichloroethane*	30 μg/L		nd
1,1,1 trichloroethane*	270 μg/L		nd
Trans-1,2 dichloroethene+	100 µg/L		nd
Cis-1,2 dichloroethene*	70 µg/L		2
Trichloroethene*	330 μg/L		3
Tetrachloroethene*	70 μg/L		2

#### Table 1 – Monitoring Results (µg/L, unless specified otherwise)

nd = not detected above Laboratory NATA accreditation level of detection.

\* Criteria taken from Australian and New Zealand Guidelines for Fresh and Marine Water Quality Guidelines 2000, marine waters at 95% protection. In the absence of high reliability trigger value, the moderate or low reliability trigger guideline concentration has been quoted.

\*\* Criteria taken from Dutch Intervention Levels (Ministry of Housing and the Environmental, 2000).

 $\ast\ast\ast$  GIL for Marine Waters has been utilised as no value is available for Fresh Waters.

\*\*\*\* Trigger and Action levels to be taken into context with regional influences.

+ Derived from the US EPA Regional Screening Levels.

#### Refer to Attachment 1 - NATA Certified Analytical Data.



Laboratory analysis recorded concentrations of Electrical Conductivity and Zinc above the adopted discharge criteria. The results are considered to be ubiquitous with the expected regional background concentrations associated with the Botany aquifer. In general the heavy metal and Electrical Conductivity results are minor in exceedance to the criteria and are not expected to pose an unacceptable risk to health or the environment.

Additionally the recorded levels of Zinc are not uncommon in a stormwater system due to the effect of urban environment runoff. The ANZECC 2000 trigger values Guidelines are a Tier 1 screening risk assessment. The trigger values are a conservative in measure and generally do not take into account the effects of urban environment runoff.

It is also considered that the recorded Electrical Conductivity concentrations do not prohibit groundwater discharge to stormwater as the receiving waters (Botany Bay) are a saline environment.

No other exceedances were noted for heavy metals and all other concentrations were less than the Laboratory Limit of Reporting or did not exceed the adopted criteria. On the basis of this information, it is considered that dewatering practices have not impacted on-site water quality and that groundwater dewatering may continue in this manner or alternatively discharge to the reinjection area already established on Site.

Monitoring will continue to be undertaken by DLA during the next phase of dewatering works to further manage all potential risks associated with the dewatering exercise.

Yours faithfully,

#### DLA ENVIRONMENTAL SERVICES

John Browne Environmental Consultant



ATTACHMENT 1 – NATA CERTIFIED ANALYTICAL DATA



email: sydney@envirolab.com.au envirolab.com.au

Envirolab Services Pty Ltd - Sydney | ABN 37 112 535 645

#### **CERTIFICATE OF ANALYSIS**

142043

/

22/02/2016

#### **DLA Environmental Services Pty Ltd**

Unit 3, 38 Leighton PI Hornsby NSW 2077

Attention: John

Client:

#### Sample log in details:

Your Reference: DL3541, Banksmeadow No. of samples: 1 Water Date samples received / completed instructions received 22/02/2016

#### Analysis Details:

Please refer to the following pages for results, methodology summary and quality control data. Samples were analysed as received from the client. Results relate specifically to the samples as received. Results are reported on a dry weight basis for solids and on an as received basis for other matrices. Please refer to the last page of this report for any comments relating to the results.

#### **Report Details:**

Date results requested by: / Issue Date: 29/02/16 29/02/16 / Date of Preliminary Report: Not Issued NATA accreditation number 2901. This document shall not be reproduced except in full. Accredited for compliance with ISO/IEC 17025. Tests not covered by NATA are denoted with \*.

#### **Results Approved By:**

Jacinta/Hurst

Laboratory Manager



VHC's in water Our Reference:UNITS142043-1 DWYour ReferenceDWDate Sampled-19/02/2016 WaterDate Sample-24/02/2016 WaterDate extracted-24/02/2016 Uate analysedDate analysed-25/02/2016Dichlorodifluoromethaneµg/L<10 Vinyl ChlorideVinyl Chlorideµg/L<10 Ug/LChloroethaneµg/L<10 Trichlorofluoromethaneµg/L<10 Chloroethaneµg/L<10 Trichlorofluoromethaneµg/L<10 1,1-Dichloroetheneµg/L<10 1,1-Dichloroetheneµg/L<1 1,1-dichloroethaneµg/L<1 1,1-dichloroetheneµg/L<1 Gis-1,2-dichloroetheneµg/L<1 Bromochloromethaneµg/L<1Q/L<1<1Use-1,2-dichloroetheneµg/L<1Use-1,2-dichloroetheneµg/L<1Use-1,2-dichloroetheneµg/L<1Use-1,2-dichloroetheneµg/L<1
Your ReferenceDWDate Sampled-19/02/2016Type of sample-19/02/2016Date extracted-24/02/2016Date analysed-25/02/2016Dichlorodifluoromethaneµg/L<10
Date Sampled Type of sample-19/02/2016 WaterDate extracted-24/02/2016Date analysed-25/02/2016Dichlorodifluoromethaneµg/L<10
Type of sampleWaterDate extracted-24/02/2016Date analysed-25/02/2016Dichlorodifluoromethaneμg/L<10
Date extracted-24/02/2016Date analysed-25/02/2016Dichlorodifluoromethaneμg/L<10
Date analysed- $25/02/2016$ Dichlorodifluoromethane $\mu g/L$ <10
Dichlorodifluoromethaneμg/L<10Chloromethaneμg/L<10
Chloromethaneµg/L<10Vinyl Chlorideµg/L<10
Chloromethane $\mu g/L$ <10Vinyl Chloride $\mu g/L$ <10
Vinyl Chloride $\mu$ g/L<10Bromomethane $\mu$ g/L<10
Bromomethaneμg/L<10Chloroethaneμg/L<10
Chloroethaneµg/L<10Trichlorofluoromethaneµg/L<10
Trichlorofluoromethaneμg/L<101,1-Dichloroetheneμg/L<1
1,1-Dichloroetheneµg/L<1Trans-1,2-dichloroetheneµg/L<1
Trans-1,2-dichloroetheneμg/L<11,1-dichloroethaneμg/L<1
1,1-dichloroethaneμg/L<1Cis-1,2-dichloroetheneμg/L3
Cis-1,2-dichloroethene µg/L 3
Chloroform ua/L 2
13
1,1,1-trichloroethane µg/L <1
1,1-dichloropropene µg/L <1
Carbon tetrachloride µg/L <1
Dibromomethane µg/L <1
1,2-dichloropropane µg/L <1
Trichloroethene µg/L 3
Bromodichloromethane µg/L <1
trans-1,3-dichloropropene µg/L <1
cis-1,3-dichloropropene µg/L <1
1,1,2-trichloroethane µg/L <1
1,3-dichloropropane µg/L <1
Dibromochloromethane µg/L <1
1,2-dibromoethane µg/L <1
Tetrachloroethene µg/L 2
1,1,1,2-tetrachloroethane µg/L <1
Chlorobenzene µg/L <1
Bromoform µg/L <1
1,1,2,2-tetrachloroethane µg/L 2
1,2,3-trichloropropane µg/L <1
Bromobenzene µg/L <1
2-chlorotoluene µg/L <1
4-chlorotoluene µg/L <1
1,3-dichlorobenzene µg/L <1
1,4-dichlorobenzene µg/L <1
1,2-dichlorobenzene µg/L <1

Envirolab Reference: 142043 Revision No: R 00

VHC's in water		
Our Reference:	UNITS	142043-1
Your Reference		DW
	-	
Date Sampled		19/02/2016
Type of sample		Water
1,2-dibromo-3-chloropropane	µg/L	<1
1,2,4-trichlorobenzene	µg/L	<1
Hexachlorobutadiene	µg/L	<1
1,2,3-trichlorobenzene	µg/L	<1
Surrogate Dibromofluoromethane	%	97
Surrogate toluene-d8	%	96
Surrogate 4-BFB	%	97

vTRH(C6-C10)/BTEXN in Water		
Our Reference:	UNITS	142043-1
Your Reference		DW
	-	
Date Sampled		19/02/2016
Type of sample		Water
Date extracted	-	24/02/2016
Date analysed	-	25/02/2016
TRHC6 - C9	µg/L	12
TRHC6 - C10	µg/L	13
TRHC6 - C10 less BTEX (F1)	µg/L	13
Benzene	µg/L	<1
Toluene	µg/L	<1
Ethylbenzene	µg/L	<1
m+p-xylene	µg/L	<2
o-xylene	µg/L	<1
Naphthalene	µg/L	<1
Surrogate Dibromofluoromethane	%	101
Surrogate toluene-d8	%	96
Surrogate 4-BFB	%	97

svTRH (C10-C40) in Water		
Our Reference:	UNITS	142043-1
Your Reference		DW
	-	
Date Sampled		19/02/2016
Type of sample		Water
Date extracted	-	24/02/2016
Date analysed	-	25/02/2016
TRHC 10 - C14	µg/L	<50
TRHC 15 - C28	µg/L	<100
TRHC29 - C36	µg/L	<100
TRH>C10 - C16	µg/L	<50
TRH>C10 - C16 less Naphthalene (F2)	µg/L	<50
TRH>C16 - C34	µg/L	<100
TRH>C34 - C40	µg/L	<100
Surrogate o-Terphenyl	%	105

PAHs in Water		1 100 10 1
Our Reference:	UNITS	142043-1 DW
Your Reference		Dvv
Date Sampled		19/02/2016
Type of sample		Water
Date extracted	-	24/02/2016
Date analysed	-	24/02/2016
Naphthalene	µg/L	<1
Acenaphthylene	µg/L	<1
Acenaphthene	µg/L	<1
Fluorene	µg/L	<1
Phenanthrene	µg/L	<1
Anthracene	µg/L	<1
Fluoranthene	µg/L	<1
Pyrene	µg/L	<1
Benzo(a)anthracene	µg/L	<1
Chrysene	µg/L	<1
Benzo(b,j+k)fluoranthene	µg/L	<2
Benzo(a)pyrene	µg/L	<1
Indeno(1,2,3-c,d)pyrene	µg/L	<1
Dibenzo(a,h)anthracene	µg/L	<1
Benzo(g,h,i)perylene	µg/L	<1
Benzo(a)pyrene TEQ	µg/L	<5
Total +ve PAH's	µg/L	NIL(+)VE
Surrogate p-Terphenyl-d14	%	118

HM in water - dissolved		
Our Reference:	UNITS	142043-1
Your Reference		DW
	-	
Date Sampled		19/02/2016
Type of sample		Water
Date prepared	-	23/02/2016
Date analysed	-	23/02/2016
Arsenic-Dissolved	µg/L	3
Cadmium-Dissolved	µg/L	<0.1
Chromium-Dissolved	µg/L	2
Copper-Dissolved	µg/L	<1
Lead-Dissolved	µg/L	<1
Mercury-Dissolved	µg/L	0.18
Nickel-Dissolved	µg/L	2
Zinc-Dissolved	µg/L	20

#### **Client Reference:**

#### DL3541, Banksmeadow

Miscellaneous Inorganics		
Our Reference:	UNITS	142043-1
Your Reference		DW
	-	
Date Sampled		19/02/2016
Type of sample		Water
Date prepared	-	22/02/2016
Date analysed	-	22/02/2016
Date analysed pH	- pHUnits	22/02/2016 7.2
,	- pH Units µS/cm	

#### Client Reference: DL3541, Banksmeadow

MethodID	Methodology Summary
Org-013	Water samples are analysed directly by purge and trap GC-MS.
Org-016	Soil samples are extracted with methanol and spiked into water prior to analysing by purge and trap GC-MS. Water samples are analysed directly by purge and trap GC-MS. F1 = (C6-C10)-BTEX as per NEPM B1 Guideline on Investigation Levels for Soil and Groundwater.
Org-003	Soil samples are extracted with Dichloromethane/Acetone and waters with Dichloromethane and analysed by GC-FID.
	F2 = (>C10-C16)-Naphthalene as per NEPM B1 Guideline on Investigation Levels for Soil and Groundwater (HSLs Tables 1A (3, 4)). Note Naphthalene is determined from the VOC analysis.
Org-012	Soil samples are extracted with Dichloromethane/Acetone and waters with Dichloromethane and analysed by GC-MS. Benzo(a)pyrene TEQ as per NEPM B1 Guideline on Investigation Levels for Soil and Groundwater - 2013.
Metals-022 ICP-MS	Determination of various metals by ICP-MS.
Metals-021 CV- AAS	Determination of Mercury by Cold Vapour AAS.
Inorg-001	pH - Measured using pH meter and electrode in accordance with APHA latest edition, 4500-H+. Please note that the results for water analyses are indicative only, as analysis outside of the APHA storage times.
Inorg-002	Conductivity and Salinity - measured using a conductivity cell at 25oC in accordance with APHA latest edition 2510 and Rayment & Lyons.
Inorg-019	Suspended Solids - determined gravimetrcially by filtration of the sample. The samples are dried at 104+/-5oC.

		Clie	nt Referenc	e: D	L3541, Bank	smeadow		
QUALITY CONTROL	UNITS	PQL	METHOD	Blank	Duplicate Sm#	Duplicate results	Spike Sm#	Spike % Recovery
VHC's in water						Base II Duplicate II % RPD		
Date extracted	-			24/02/2 016	142043-1	24/02/2016  24/02/2016	LCS-W2	24/02/2016
Date analysed	-			25/02/2 016	142043-1	25/02/2016  25/02/2016	LCS-W2	25/02/2016
Dichlorodifluoromethane	µg/L	10	Org-013	<10	142043-1	<10  <10	[NR]	[NR]
Chloromethane	µg/L	10	Org-013	<10	142043-1	<10  <10	[NR]	[NR]
Vinyl Chloride	µg/L	10	Org-013	<10	142043-1	<10  <10	[NR]	[NR]
Bromomethane	µg/L	10	Org-013	<10	142043-1	<10  <10	[NR]	[NR]
Chloroethane	µg/L	10	Org-013	<10	142043-1	<10  <10	[NR]	[NR]
Trichlorofluoromethane	µg/L	10	Org-013	<10	142043-1	<10  <10	[NR]	[NR]
1,1-Dichloroethene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Trans-1,2- dichloroethene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,1-dichloroethane	µg/L	1	Org-013	<1	142043-1	<1  <1	LCS-W2	94%
Cis-1,2-dichloroethene	µg/L	1	Org-013	<1	142043-1	3  3  RPD:0	[NR]	[NR]
Bromochloromethane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Chloroform	µg/L	1	Org-013	<1	142043-1	2  2  RPD:0	LCS-W2	96%
2,2-dichloropropane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,2-dichloroethane	µg/L	1	Org-013	<1	142043-1	<1  <1	LCS-W2	94%
1,1,1-trichloroethane	µg/L	1	Org-013	<1	142043-1	<1  <1	LCS-W2	96%
1,1-dichloropropene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Carbon tetrachloride	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Dibromomethane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,2-dichloropropane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Trichloroethene	µg/L	1	Org-013	<1	142043-1	3  3  RPD:0	LCS-W2	97%
Bromodichloromethane	µg/L	1	Org-013	<1	142043-1	<1  <1	LCS-W2	96%
trans-1,3- dichloropropene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
cis-1,3-dichloropropene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,1,2-trichloroethane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,3-dichloropropane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Dibromochloromethane	µg/L	1	Org-013	<1	142043-1	<1  <1	LCS-W2	99%
1,2-dibromoethane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Tetrachloroethene	µg/L	1	Org-013	<1	142043-1	2  2  RPD:0	LCS-W2	101%
1,1,1,2- tetrachloroethane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Chlorobenzene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Bromoform	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,1,2,2- tetrachloroethane	µg/L	1	Org-013	<1	142043-1	2  1  RPD:67	[NR]	[NR]
1,2,3-trichloropropane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Bromobenzene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
2-chlorotoluene	μg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
4-chlorotoluene	μg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,3-dichlorobenzene	μg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,4-dichlorobenzene	μg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,2-dichlorobenzene	μg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]

QUALITYCONTROL	UNITS	PQL	METHOD	Blank	Duplicate	Duplicate results	Spike Sm#	Spike %
					Sm#			Recovery
VHC's in water						Base II Duplicate II % RPD		
1,2-dibromo-3- chloropropane	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,2,4-trichlorobenzene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
Hexachlorobutadiene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
1,2,3-trichlorobenzene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
<i>Surrogate</i> Dibromofluoromethane	%		Org-013	96	142043-1	97  99  RPD:2	LCS-W2	101%
Surrogate toluene-d8	%		Org-013	98	142043-1	96  97  RPD: 1	LCS-W2	101%
Surrogate 4-BFB	%		Org-013	96	142043-1	97  99  RPD:2	LCS-W2	101%
QUALITYCONTROL	UNITS	PQL	METHOD	Blank	Duplicate Sm#	Duplicate results	Spike Sm#	Spike % Recovery
vTRH(C6-C10)/BTEXNin Water						Base II Duplicate II %RPD		
Date extracted	-			24/02/2 016	142043-1	24/02/2016  24/02/2016	LCS-W2	24/02/2016
Date analysed	-			25/02/2 016	142043-1	25/02/2016  25/02/2016	LCS-W2	25/02/2016
TRHC6 - C9	µg/L	10	Org-016	<10	142043-1	12  11  RPD:9	LCS-W2	99%
TRHC6 - C10	µg/L	10	Org-016	<10	142043-1	13  14  RPD:7	LCS-W2	99%
Benzene	µg/L	1	Org-016	<1	142043-1	<1  <1	LCS-W2	98%
Toluene	µg/L	1	Org-016	<1	142043-1	<1  <1	LCS-W2	97%
Ethylbenzene	µg/L	1	Org-016	<1	142043-1	<1  <1	LCS-W2	101%
m+p-xylene	µg/L	2	Org-016	<2	142043-1	<2  <2	LCS-W2	100%
o-xylene	µg/L	1	Org-016	<1	142043-1	<1  <1	LCS-W2	100%
Naphthalene	µg/L	1	Org-013	<1	142043-1	<1  <1	[NR]	[NR]
<i>Surrogate</i> Dibromofluoromethane	%		Org-016	103	142043-1	101  99  RPD:2	LCS-W2	98%
Surrogate toluene-d8	%		Org-016	98	142043-1	96    97    RPD: 1	LCS-W2	101%
Surrogate 4-BFB	%		Org-016	96	142043-1	97  99  RPD:2	LCS-W2	101%

QUALITYCONTROL	UNITS	PQL	METHOD	Blank	Duplicate	Duplicate results	Spike Sm#	Spike %
svTRH (C10-C40) in Water					Sm#	Base II Duplicate II %RPD		Recovery
Date extracted	-			24/02/2 016	[NT]	[NT]	LCS-W2	24/02/2016
Date analysed	-			25/02/2 016	[NT]	[NT]	LCS-W2	25/02/2016
TRHC 10 - C14	µg/L	50	Org-003	<50	[NT]	[NT]	LCS-W2	102%
TRHC 15 - C28	µg/L	100	Org-003	<100	[NT]	[NT]	LCS-W2	119%
TRHC29 - C36	µg/L	100	Org-003	<100	[NT]	[NT]	LCS-W2	106%
TRH>C10 - C16	µg/L	50	Org-003	<50	[NT]	[NT]	LCS-W2	102%
TRH>C16 - C34	µg/L	100	Org-003	<100	[NT]	[NT]	LCS-W2	119%
TRH>C34 - C40	µg/L	100	Org-003	<100	[NT]	[NT]	LCS-W2	106%
Surrogate o-Terphenyl	%		Org-003	99	[NT]	[NT]	LCS-W2	116%
QUALITYCONTROL	UNITS	PQL	METHOD	Blank	Duplicate Sm#	Duplicate results	Spike Sm#	Spike % Recovery
PAHs in Water						Base II Duplicate II % RPD		
Date extracted	-			24/02/2 016	[NT]	[NT]	LCS-W2	24/02/2016
Date analysed	-			24/02/2 016	[NT]	[NT]	LCS-W2	24/02/2016
Naphthalene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	89%
Acenaphthylene	µg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Acenaphthene	µg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Fluorene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	96%
Phenanthrene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	94%
Anthracene	µg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Fluoranthene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	86%
Pyrene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	90%
Benzo(a)anthracene	µg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Chrysene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	101%
Benzo(b,j+k) fluoranthene	µg/L	2	Org-012	<2	[NT]	[NT]	[NR]	[NR]
Benzo(a)pyrene	µg/L	1	Org-012	<1	[NT]	[NT]	LCS-W2	99%
Indeno(1,2,3-c,d)pyrene	µg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Dibenzo(a,h)anthracene	µg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Benzo(g,h,i)perylene	μg/L	1	Org-012	<1	[NT]	[NT]	[NR]	[NR]
Surrogate p-Terphenyl- d14	%		Org-012	132	[NT]	[NT]	LCS-W2	103%

		Clie	nt Referenc	e: Di	L3541, Banks	smeadow		
QUALITYCONTROL	UNITS	PQL	METHOD	Blank	Duplicate Sm#	Duplicate results	Spike Sm#	Spike % Recovery
HM in water - dissolved						Base II Duplicate II % RPD		
Date prepared	-			23/02/2 016	[NT]	[NT]	LCS-W1	23/02/2016
Date analysed	-			23/02/2 016	[NT]	[NT]	LCS-W1	23/02/2016
Arsenic-Dissolved	µg/L	1	Metals-022 ICP-MS	<1	[NT]	[NT]	LCS-W1	98%
Cadmium-Dissolved	µg/L	0.1	Metals-022 ICP-MS	<0.1	[NT]	[NT]	LCS-W1	102%
Chromium-Dissolved	µg/L	1	Metals-022 ICP-MS	<1	[NT]	[NT]	LCS-W1	94%
Copper-Dissolved	µg/L	1	Metals-022 ICP-MS	<1	[NT]	[NT]	LCS-W1	100%
Lead-Dissolved	µg/L	1	Metals-022 ICP-MS	<1	[NT]	[NT]	LCS-W1	107%
Mercury-Dissolved	µg/L	0.05	Metals-021 CV-AAS	<0.05	[NT]	[NT]	LCS-W1	100%
Nickel-Dissolved	µg/L	1	Metals-022 ICP-MS	<1	[NT]	[NT]	LCS-W1	98%
Zinc-Dissolved	µg/L	1	Metals-022 ICP-MS	<1	[NT]	[NT]	LCS-W1	98%
QUALITYCONTROL	UNITS	PQL	METHOD	Blank	Duplicate	Duplicate results	Spike Sm#	Spike %
Miscellaneous Inorganics					Sm#	Base II Duplicate II % RPD		Recovery
Date prepared	-			22/02/2 016	[NT]	[NT]	LCS-W1	22/02/2016
Date analysed	-			22/02/2 016	[NT]	[NT]	LCS-W1	22/02/2016
рН	pHUnits		Inorg-001	[NT]	[NT]	[NT]	LCS-W1	100%
Electrical Conductivity	µS/cm	1	Inorg-002	<1	[NT]	[NT]	LCS-W1	103%
Total Suspended Solids	mg/L	5	Inorg-019	⊲5	[NT]	[NT]	LCS-W1	82%

#### **Report Comments:**

Asbestos ID was analysed by Approved Identifier: Asbestos ID was authorised by Approved Signatory: Not applicable for this job Not applicable for this job

INS: Insufficient sample for this test NR: Test not required <: Less than PQL: Practical Quantitation Limit RPD: Relative Percent Difference >: Greater than NT: Not tested NA: Test not required LCS: Laboratory Control Sample

#### **Quality Control Definitions**

**Blank**: This is the component of the analytical signal which is not derived from the sample but from reagents, glassware etc, can be determined by processing solvents and reagents in exactly the same manner as for samples. **Duplicate**: This is the complete duplicate analysis of a sample from the process batch. If possible, the sample selected should be one where the analyte concentration is easily measurable.

**Matrix Spike** : A portion of the sample is spiked with a known concentration of target analyte. The purpose of the matrix spike is to monitor the performance of the analytical method used and to determine whether matrix interferences exist.

LCS (Laboratory Control Sample) : This comprises either a standard reference material or a control matrix (such as a blank sand or water) fortified with analytes representative of the analyte class. It is simply a check sample.

**Surrogate Spike:** Surrogates are known additions to each sample, blank, matrix spike and LCS in a batch, of compounds which are similar to the analyte of interest, however are not expected to be found in real samples.

#### Laboratory Acceptance Criteria

Duplicate sample and matrix spike recoveries may not be reported on smaller jobs, however, were analysed at a frequency to meet or exceed NEPM requirements. All samples are tested in batches of 20. The duplicate sample RPD and matrix spike recoveries for the batch were within the laboratory acceptance criteria.

Filters, swabs, wipes, tubes and badges will not have duplicate data as the whole sample is generally extracted during sample extraction.

Spikes for Physical and Aggregate Tests are not applicable.

For VOCs in water samples, three vials are required for duplicate or spike analysis.

Duplicates: <5xPQL - any RPD is acceptable; >5xPQL - 0-50% RPD is acceptable. Matrix Spikes, LCS and Surrogate recoveries: Generally 70-130% for inorganics/metals; 60-140% for organics (+/-50% surrogates) and 10-140% for labile SVOCs (including labile surrogates), ultra trace organics and speciated phenols is acceptable.

In circumstances where no duplicate and/or sample spike has been reported at 1 in 10 and/or 1 in 20 samples respectively, the sample volume submitted was insufficient in order to satisfy laboratory QA/QC protocols.

When samples are received where certain analytes are outside of recommended technical holding times (THTs), the analysis has proceeded. Where analytes are on the verge of breaching THTs, every effort will be made to analyse within the THT or as soon as practicable.

Where sampling dates are not provided, Envirolab are not in a position to comment on the validity of the analysis where recommended technical holding times may have been breached.



Page: Page 35 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016

PLAN

Soil, Water and Leachate Management

Appendix E Long Term Environmental Management Plan





## **Environmental Management Plan**

34-36 McPherson Street Banksmeadow NSW 2019

Lipman Pty Ltd

DL3541\_S004923

July 2016



PROJECT NAME	Veolia Waste Transfer Facility - 34-36 McPherson Street, Banksmeadow, NSW.
PROJECT ID	DL3541
DOCUMENT CONTROL NUMBER	S004923
PREPARED FOR	Lipman Pty Ltd
APPROVED FOR RELEASE BY	David Lane
DISCLAIMER AND COPYRIGHT	This report is subject to the copyright statement located at www.pacific-environment.com © Pacific Environment Operations Pty Ltd ABN 86 127 101 642

DOCUMENT CONTROL							
VERSION	DATE	COMMENT	PREPARED BY	REVIEWED BY			
Version 1.0	17.05.2016	Draft Copy for Audit Review	John Browne	David Lane			
Revision 1.0	26.06.2016	Following Interim Audit Advice dated 26 <sup>th</sup> May 2016	John Browne	David Lane			
Revision 2.0	13.07.2016	Following Interim Audit Advice dated 7 <sup>th</sup> July 2016	John Browne	David Lane			
Revision 2.1	19.07.2016	Following Interim Audit Advice dated 19 <sup>th</sup> July 2016	John Browne	David Lane			

DLA Environmental Services Pty Ltd: ABN 80 601 661 634

#### BRISBANE

Level 19, Queen Street Brisbane, Qld 4000 Ph: +61 7 3004 6400

Unit 1, 22 Varley Street Yeerongpilly, Qld 4105 Ph: +61 7 3004 6460

#### ADELAIDE

35 Edward Street, Norwood SA 5067 PO Box 3187, Norwood, SA 5067 Ph: +61 8 8332 0960 Fax: +61 7 3844 5858

#### PERTH

Level 1, Suite 3 34 Queen Street, Perth, WA 6000 Ph: +61 8 9481 4961 Fax: +61 2 9870 0999

#### SYDNEY

Suite 1, Level 1, 146 Arthur Street North Sydney, NSW 2060 Ph: +61 2 9870 0900 Fax: +61 2 9870 0999

#### DLA ENVIRONMENTAL SERVICES

Unit 3, 38 Leighton Place Hornsby, NSW 2077 Ph: +61 2 9476 1765 Fax: +61 2 9476 1557

42B Church St Maitland NSW 2320 Ph: +61 2 4933 0001

#### MELBOURNE

Level 10, 224 Queen Street Melbourne, Vic 3000 Ph: +61 3 9036 2637 Fax: +61 2 9870 0999



## **TABLE OF CONTENTS**

1.0	INTRODUCTION	1
1.1	.1 General	
1.2	.2 Objectives	
1.3	.3 EMP Audience	2
2.0	SITE DESCRIPTION	1
3.0	SUMMARY OF CONTAMINATION	2
3.1	.1 Contaminants of Potential Concern	2
3.2	.2 Asbestos in Service Trenches	2
3.3	.3 Exposure and Risks to Human Healt	h2
4.0	CAPPING AND CONTAINMENT	5
4.1	.1 Areas of Deep Imported Fill	5
4.2	.2 Areas of Shallow Imported Fill	5
4.3	.3 Areas of Soft Landscaping	5
5.0	HIERARCHY AND RESPONSIBILITIES	6
5.1	.1 Management Body	6
5.1 5.2	<b>c</b> ,	
	.2 Responsibilities of Management Bo	
5.2	<ul><li>.2 Responsibilities of Management Bo</li><li>.3 Site Inspection Report</li></ul>	dy6
5.2 5.3	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> </ul>	dy6
5.2 5.3 5.4	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> </ul>	dy6 7 7
5.2 5.3 5.4 <b>6.0</b>	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> <li>5.1 Maintenance of the Containment S</li> </ul>	dy6 7 7
5.2 5.3 5.4 <b>6.0</b> 6.1 6.2	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> <li>.1 Maintenance of the Containment S</li> <li>.2 Future Works On-Site</li> </ul>	dy
5.2 5.3 5.4 6.0 6.1 6.2 6	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> <li>.1 Maintenance of the Containment S</li> <li>.2 Future Works On-Site</li> <li>6.2.1 Landscaping Works</li> </ul>	dy
5.2 5.3 5.4 6.0 6.1 6.2 6 6	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> <li>.1 Maintenance of the Containment S</li> <li>.2 Future Works On-Site</li> <li>6.2.1 Landscaping Works</li> <li>6.2.2 Intrusive Works Above the Ma</li> </ul>	dy
5.2 5.3 5.4 6.0 6.1 6.2 6 6	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> <li>5.1 Maintenance of the Containment S</li> <li>5.2 Future Works On-Site</li> <li>6.2.1 Landscaping Works</li> <li>6.2.2 Intrusive Works Above the Ma</li> <li>6.2.3 Intrusive Works Below the Ma</li> </ul>	dy
5.2 5.3 5.4 6.0 6.1 6.2 6 6 6 6.3	<ul> <li>.2 Responsibilities of Management Bo</li> <li>.3 Site Inspection Report</li> <li>.4 Site-Specific Awareness</li> <li>.4 Site-Specific Awareness</li> <li>.4 Maintenance of the Containment S</li> <li>.1 Maintenance of the Containment S</li> <li>.2 Future Works On-Site</li> <li>6.2.1 Landscaping Works</li> <li>6.2.2 Intrusive Works Above the Ma</li> <li>6.2.3 Intrusive Works Below the Ma</li> <li>.3 Land Re-Use or Redevelopment</li> </ul>	dy
5.2 5.3 5.4 6.0 6.1 6.2 6 6 6.3 6.3	<ul> <li>2 Responsibilities of Management Bo</li> <li>3 Site Inspection Report</li> <li>4 Site-Specific Awareness</li> <li>MANAGEMENT CONTROLS</li> <li>Maintenance of the Containment S</li> <li>Future Works On-Site</li> <li>6.2.1 Landscaping Works</li> <li>6.2.2 Intrusive Works Above the Ma</li> <li>6.2.3 Intrusive Works Below the Ma</li> <li>3.3 Land Re-Use or Redevelopment</li> <li>6.3.1 Resale</li> </ul>	dy



7.1	Auditing	. 16
7.2	On-Going Applicability	.16
7.3	Current Emergency Contact	.16

## **FIGURES**

Figure 1	Site Location
Figure 2	Site Development Plan
Figure 3	Fill Depths and Marker Layer
Figure 4	Site Surface Finishes and layout
Figure 5	Services Plan
Figure 6	Landscaping Areas

## **APPENDICES**

Appendix A	Veolia Acknowledgement Letter
Appendix B	Unexpected Finds Protocol



## **1.0 INTRODUCTION**

#### 1.1 General

DLA Environmental Services (DLA) was commissioned by Lipman Pty Ltd to perform a Validation Assessment for the property identified as:

#### 34-36 McPherson Street, Banksmeadow NSW 2019 (the Site).

The project objectives of the Validation Report are to demonstrate that the Site is suitable for the proposed future land use, in accordance with the objectives of the remediation strategy developed for the Site.

From the results of previous assessments, it was apparent that friable asbestos appeared to be present in the absence of significant bonded asbestos and was relatively widespread or randomly distributed in heterogeneous fill across the Site at low concentrations. DLA considered that asbestos at the Site will not pose a risk to human health as long as it remains undisturbed beneath the proposed development. A major component of the remediation and validation program therefore entailed management of the asbestos risk through capping and containing the Site with the new development.

To assist with maintaining protection from, and restricting inadvertent contact to, potential contamination in residual soils at the Site, an Environmental Management Plan (EMP) has been prepared for the Site. The EMP has been developed in accordance with the *Guideline for the Preparation of Environmental Management Plans* (DIPNR, 2004).

#### **1.2 Objectives**

The principal objectives of the EMP are as follows:

- Define details of who, what, where and when ongoing management and environmental mitigation measures are to be implemented;
- To provide Site manager or owner, government agencies, contractors, developers and other stakeholders better onsite environmental management control over the life of the property;
- Allow property managers to ensure their contractors fulfil environmental obligations on their behalf; and,



 Demonstrate due diligence by providing guidance on any excavation/disturbance of the soil within the subject area and therefore prevent any adverse impacts on human health or the environment.

#### **1.3 EMP Audience**

The EMP has been developed to address the management of site-specific environmental concerns associated with the potential for residual contamination at the Site. Asbestos fibres pose a risk to maintenance workers accessing services. Service trenches are the most likely part of the Site to be accessed in the future. The presence of asbestos impacted fill in service trenches and the corresponding control measures are therefore more relevantly directed at future maintenance workers.

Management protocols in this EMP are also relevant to:

- Future Site managers and owners;
- Future construction workers; and,
- Future resale/redevelopment agencies.

Although a potential for exposure to contamination by Site visitors and occupants cannot be discounted, the likelihood of this occurrence is anticipated to be low considering the land use scenario. Future Site visitors and occupants are not specifically relevant to this EMP due to the use of the Site as Waste Transfer Facility.



## 2.0 SITE DESCRIPTION

The Site identification details are summarised in Table 2a below:

ITEMS	DETAILS
Site Name	Veolia Waste Transfer Facility
Address	34-36 McPherson Street
Local Government Authority	City of Botany Bay
Lot and Deposited Plan	Lots A & B, D.P. 366725 and Lot 1, D.P. 435497
Development Controls	Botany Bay Local Environmental Plan 2013
Site Zoning	MD – SEPP (Major Development) 2005
Current Use (NEPM 2013 Table 1A(1))	Commercial/Industrial
Proposed Use (NEPM 2013 Table 1A(1))	Commercial/Industrial
Site Area (approx.)	9,800 m <sup>2</sup> (0.98 ha)
Locality Map	Refer to <b>Figure 1</b> – Site Location

Refer to **Figure 1** – Site Location and **Figure 2** – Site Development Plan.



## 3.0 SUMMARY OF CONTAMINATION

#### 3.1 Contaminants of Potential Concern

DLA undertook an asbestos quantification assessment concurrent to the completion of the RAP. The objective of that assessment was to quantify the concentrations of asbestos in in-situ soils and to evaluate the potential for any unacceptable risks to human health or the environment with regards to the presence of asbestos in soils. The report drew conclusions on the land use suitability of the Site with regards to asbestos contamination and provided recommendations to enable such conclusions for integration into the RAP developed for the Site.

Asbestos quantification analysis was undertaken at all 17 sample locations with a total of 37 primary samples collected with an additional four duplicate samples. Fill soils were field screened with suspected Asbestos Containing Materials (ACM) retained on the sieve screen in two test pits. Laboratory analysis later confirmed that all fragments retained above the sieve did not contain asbestos.

Following field screening, soils were laboratory tested for Asbestos Fines / Friable Asbestos (AF/FA) content. AF/FA detections were recorded in eight of the 41 samples analysed. Concentrations were reported in excess of Health Screening Levels (HSLs) in one test pit location for two samples – S24 TP14 (0.2-0.4m) and S25 TP14 (0.5-1.5m). Concentrations of AF/FA were reported at 0.001% w/w in S3 TP-3 (0.1-0.6m) and S20 TP11 (0.8-0.9m). All other areas of the Site reported detections of AF/FA orders of magnitude below the adopted HSL or less than the laboratory limit of reporting.

From the results, it was apparent that AF/FA appeared to be present in the absence of significant ACM and was relatively widespread or randomly distributed in heterogeneous fill across the Site at low concentrations.

#### **3.2** Asbestos in Service Trenches

Fill materials sourced from the Site which have a potential to contain asbestos have been used to backfill service trenches. Asbestos fibres pose a risk to maintenance workers accessing services. Service trenches are the most likely part of the Site to be accessed in the future.

#### 3.3 Exposure and Risks to Human Health

Considering asbestos is the principal contaminant of concern, the relevant release and transport mechanism is primarily limited to in-situ disturbance in soils and subsequent dispersion into air.



Asbestos does not have the capacity to leach into soils or groundwater and when confined to the soil matrix and absent of external disturbance, the contaminant is generally non-mobile. Based on asbestos being identified as the principal contaminant of concern and future potential site development activities, the relevant exposure pathway for the Site's use is inhalation of asbestos-contaminated dust.

The potential sensitive receptors of environmental impacts present at the Site include:

- Present and future workers of the Site, who may potentially be exposed to asbestos fibres through inhalation of dust associated with disturbed and impacted soils;
- Present and future workers of properties adjacent to the Site, who may potentially be exposed to asbestos fibres through inhalation of dust associated with disturbed and impacted soils;
- Maintenance workers conducting activities at the Site, who may potentially be exposed to asbestos fibres through inhalation of dust associated with disturbed and impacted soils.

Complete exposure pathways exist for present and futures works at the Site. The physical capping mechanism installed across the Site, in conjunction with long-term management controls, will significantly mitigate exposure of asbestos-impacted soils to future patients, visitors and users.

Human health risks to asbestos in soils are summarised in the document, *Managing Asbestos in or on Soil,* published by WorkCover NSW in 2014. The guide provides the following information regarding the human health risks to asbestos in soils:

"Asbestos only poses a risk to human health when elevated levels of asbestos fibres are breathed in.

The likelihood of exposure occurring depends upon the potential for the asbestos material to release fibres, whether the asbestos material is contained or covered, and any operational control measures or personal protective equipment which have been applied to limit the generation and/or inhalation of airborne fibres.

Non-friable asbestos, previously referred to as 'bonded asbestos', in sound condition represents a low human health risk. However, friable asbestos materials or damaged, crumbling bonded asbestos, have the potential to generate, or be associated with, free asbestos fibres and therefore must be carefully managed to minimise the release of asbestos fibres into the air."



The Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (Western Australia Department of Health, 2009) states:

"If deposited in the lungs, [asbestos] fibres can initiate diseases that take many years to produce major health effects. These effects include asbestosis, lung cancer and the normally rare cancer mesothelioma that affects certain chest membrane linings. These impacts tend to be the result of higher levels of exposure, most often occupational, but mesothelioma can also result from low level exposures."

## 4.0 CAPPING AND CONTAINMENT

The management strategy for the risk of asbestos in soils is through capping and containing the Site with the proposed development. The details of the capping and containment strategy are outlined below:

#### 4.1 Areas of Deep Imported Fill

For areas of deep imported fill (between 1.0m and 4.0m depth), the future disturbance of soils is unlikely under the proposed development. Capping and containing the Site with the proposed development was considered adequate for these areas.

#### 4.2 Areas of Shallow Imported Fill

The areas of shallow imported fill (between 0.1m and less than 1.0m depth), the risk of future disturbance of soils is greater under the proposed development. A marker layer (brightly coloured non-woven geotextile polyester continuous filament) was placed over in situ fill in these areas to provide adequate visual warning during any future ground disturbance. The areas were then capped and contained with the proposed development (i.e. compactor slabs, roadways and building footprints).

#### 4.3 Areas of Soft Landscaping

The areas of garden beds/soft landscaping where less than 1.0m of filling is proposed, the potential for disturbance of insitu fill materials such as through gardening and future maintenance activities is high. Soils in garden beds/soft landscaping areas were excavated to a minimum depth of 500mm. A marker layer was placed over insitu fill in these areas provides adequate visual warning during any future ground disturbance. A capping layer of minimum 500mm thick consisting of material validated as suitable for the proposed land use was installed over the marker layer in these areas.

Refer to Figure 3 – Fill Depths and Marker Layer and Figure 6 – Landscaping Areas.



### 5.0 **HIERARCHY AND RESPONSIBILITIES**

#### 5.1 Management Body

It is understood that the Site will be managed by VEOLIA. Under the *Contaminated Land Management Act 1997* (NSW), VEOLIA (nominated party) has the primary responsibility for all matters associated with the works, maintenance issues and accountability of the containment system. In this document, 'containment system' refers to the physical barriers installed at the Site to reduce exposure to the identified contaminants and includes:

- Marker Layer and 500mm of capping material in garden beds/soft landscaping areas; and,
- Marker Layer, concrete slabs, roadways and building footprints areas.

Any future use of the affected land or any building thereon shall include the detail of this management plan and clear agreement as to the responsibilities detailed above between parties.

#### 5.2 Responsibilities of Management Body


The responsibilities of VEOLIA with regard to this EMP are:

- To notify the Botany Bay City Council whenever excavation/disturbance of the ground in the subject area is required;
- To seek approval from Botany Bay City Council whenever excavation/disturbance of the ground in the subject area is required;
- Prior to intrusive works, to notify relevant personnel to any potential risks on-site and the relevant content of this document; and,
- To engage an environmental consultant to oversee the excavation/disturbance and ensure compliance with this EMP.



#### 5.3 Site Inspection Report

A Site Inspection Report must be developed to ensure that capping system controls are regularly monitored and managed for effectiveness. VEOLIA will be responsible for undertaking the inspection and report. An inspection of the capping layer should be performed on a weekly basis. **Table 5a** provides a non-exhaustive list of items to be included in the inspection checklist:



#### Table 5a – Site Inspection Checklist

#### 5.4 Site-Specific Awareness

VEOLIA will be responsible for ensuring that all personnel working on-site (including contractors and subcontractors) have received general awareness and instruction of their obligations under the EMP to ensure due diligence with environmental matters, including:

- Site induction;
- Environmental emergency response training; and,
- Familiarisation with site environmental controls;



A register will retain records of the individuals inducted, the date and a brief summary of the induction content.

Changes to the EMP will be communicated to the appropriate level of responsibility through inductions, on-going training and the issue of revised documentation (where necessary).

## 6.0 MANAGEMENT CONTROLS

The subsequent sections of this report outline Site Management Procedures. These procedures are provided to prevent potential adverse impacts to human health, Site amenity or the environment from any residual contamination at the Site. The procedures have been designed to minimise the potential for the generation of, or exposures to, asbestos in soils.

#### 6.1 Maintenance of the Containment System

To ensure that potential contamination in residual soils remains effectively isolated under the containment system, the integrity of the containment system is considered paramount. The following items address how the physical integrity of the containment system will be appropriately managed.

- **Control:** Demonstrate that the structural integrity of containment system will be maintained for the life of the Site's use.
- Monitoring: Routine weekly inspections are required for the areas where the containment system exists. The inspections should be in accordance with the Site Inspection Report checklist stipulated in Section 5.3 of this report. Particular attention must be given to the nature of the containment system and the structural characteristics of the material. Table 6a below provides examples of typical symptoms associated with issues in the integrity of the containment system.


PAVED AREA	LANDSCAPING AREA
<ul> <li>Cracking.</li> <li>Breakage.</li> <li>Debonding.</li> <li>Missing pavement.</li> <li>Unevenness of surface.</li> <li>Moisture patches.</li> <li>Localised seepage.</li> <li>Drilling/excavation.</li> </ul>	<ul> <li>Geofabric layer exposed.</li> <li>Erosion.</li> <li>Burrowing.</li> <li>Drilling/excavation.</li> </ul>



- **Responsibility:** VEOLIA will be responsible for conducting routine inspections of the containment system.
- Outcomes: Any issues with the structural integrity of the containment system (such as those listed in **Table 6a** above) will indicate a non-conformance for the purposes of this EMP.
- Action Levels: Any non-conformance in the physical qualities of the containment system will be appropriately addressed through repair, reinstatement or replacement. Any repairs to the containment system should be tested for Quality Assurance (QA) and certified to comply with the original design specifications.
- Reporting: Records should include (but are not limited to): date of inspection, items inspected, condition of item and if action is required. Records should be kept for the life of the containment system or until such time that the covenant requiring land owners to monitor and maintain the containment system is no longer in force. On completion of any improvement works to the containment system, the report should also include a description of the sealed finish compliant with the requirements of the approved Remedial Action Plan 34-36 McPherson Street (DLA, November 2015, ref: DL3541\_S003641 (Rev 2.2)).

A schematic of this process is provided below.







#### 6.2 Future Works On-Site

Approval for the works above or below the marker layer must be sought from the Site Environmental Manager or person responsible for the EMP enforcement. This EMP must be read, understood and followed by any person proposing to undertake works (maintenance of services, construction or otherwise) on the Site which involve disturbance of the containment system and/or excavation of soil. VEOLIA will be responsible for appropriately notifying workers and associated personnel of the requirement to review this document.

#### 6.2.1 Landscaping Works

All casual landscaping activities are to be restricted to the areas above the marker layer less than 0.3m bgl. Landscaping activities below the marker layer are strictly prohibited.

#### 6.2.2 Intrusive Works Above the Marker Layer

Soils above the marker layer comprise capping material validated as suitable for the Site's Commercial/Industrial land use. The risk of encountering asbestos and significant or other widespread contamination is considered to be low.

Personnel being employed to undertake any intrusive works above the marker layer must develop a specific Safe Work Method Statement (SWMS) which adequately manages the potential for exposure to contaminants in soils, including both asbestos and chemical contamination. The Unexpected Finds Protocol (**Appendix B**) is considered adequate to provide a management framework and procedure for these type of works.

#### 6.2.3 Intrusive Works Below the Marker Layer

- 1. In accordance with Clause 458 of the Work Health and Safety Regulation 2011 (NSW), only Class A asbestos removal licence holders are permitted to conduct asbestos removal work or asbestos-related work that involves friable asbestos. Considering the potential for friable asbestos in soils underlying the marker layer and within material backfilled into the service trenches, all intended asbestos removal works are required to undertaken and/or supervised by a WorkCover Class A licensed asbestos contractor.
- 2. Personal Protection Equipment (PPE) must be worn by all maintenance and construction workers including:
  - Disposable overalls;



- Respiratory protection (P2 Minimum);
- Safety boots; and,
- Hard hat.
- 3. Personnel being employed to undertake any intrusive works on the containment system must develop a specific SWMS which limits the potential for exposure to any contaminants below the barriers and ensure that the system integrity is re-instated upon completion of works. The SWMS must also adequately manage any exposure to contaminants below the barriers. Works undertaken in soils below the containment system must be undertaken by an adequately experienced Contractor and must account for all potential exposures, due to the fact that asbestos has been identified in fill material underlying the marker layer and across the whole Site at low concentrations.
- 4. The works will be undertaken works in accordance with the following:
  - Work Health and Safety Act 2011 (NSW) and associated regulations;
  - Managing Asbestos in or on soils (WorkCover NSW, 2014);
  - How to Safely Remove Asbestos Code of Practice (Safe Work Australia 2011);
  - Code of Practice for the Management and Control of Asbestos in Workplaces [NOHSC:2018] (2005); and,
  - Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres [NOHSC:3003 (2005)]
- 5. Designate the proposed service trench / excavation area. Prior to the commencement of works in the designated area, establish a 10 m exclusion zone with the installation of safety warning signs and barricade measures around the boundary.
- 6. Excavate and undertake maintenance/construction activities to the required depth, ensuring:
  - The excavator operator and transport vehicle operator within enclosed cabs are to remain inside their vehicle during the loading operation;
  - The air-conditioning is to be on 'recirculate' or switched off. If the cab is not enclosed, full PPE is to be worn;
  - Unauthorised access is to be prevented within the exclusion zone; and,
  - During the loading operation the materials are too be wetted thoroughly.
- 7. In the event that soils are excavated, allowance should be made to dispose of the excavated material in accordance with the established Waste Classification Guidelines in force at that



time. Any soil/fill excavated during onsite works, such as maintenance of underground services, must be securely stockpiled separately from the marker/barrier layer material. Where possible, stockpiles should be placed on a sealed surface or on plastic sheeting to prevent cross contamination of unsealed surfaces. If it is not possible to stockpile on a sealed or plastic covered surface, the unsealed surface within the footprint of the stockpiles must be visually inspected by a person who is appropriately qualified to recognise asbestos, and samples collected and analysed to confirm that cross-contamination has not occurred. Stockpiles must be placed in a secure location on-site and covered if they are to remain for more than 24 hours.

- 8. On completion of the works, the operators and vehicles/equipment should move to the relevant decontamination area. This includes the removal of all disposable overalls and bagging them for disposal. Vehicles should also be decontaminated. Respirators can then be removed.
- 9. It is required that an appropriate environmental professional is consulted to monitor the works and to advise on the management of exposure and methodology of works to be undertaken. Work methodologies should include appropriate notification regarding the intended level of impact on the containment system and the condition of the impacted area at the completion of works. This should also include any integrity QA certification which should be filed as a permanent record to be kept on-site, with file copies being distributed to relevant stakeholders.
- **10.** Any new service trenches should be backfilled with certified Virgin Excavated Natural Material (VENM) and appropriately re-instated.

A plan showing the location of services installed at the Site has been included as **Figure 5** of this document.

#### 6.3 Land Re-Use or Redevelopment

#### 6.3.1 Resale

If structures are to be maintained upon resale of the property, this document should form part of the sale contract information. The risk to the integrity of the containment system would therefore be minimal assuming the stipulated maintenance program is continued.



#### 6.3.2 Redevelopment

If the land is to be redeveloped by removing or refurbishing above ground structures, the process introduces a risk of compromising the effectiveness of the containment system. Prior to the commissioning of any new building, the engineered barrier surfaces and design plans should be inspected by a competent professional who can give assurance that the structures continue to comply with the original design specification.

If the containment system is to be removed as part of the development, there is a risk of exposure to, or release of, contaminated soils. It is expected that such a development would be regulated by Council Development Regulations, including obligations under SEPP 55 – Remediation of Land. Risk to human health or the environment therefore is considered to be mitigated under this circumstance by governmental regulation, which should ensure the appropriate management strategy at that time.



## 7.0 EMP REVIEW

#### 7.1 Auditing

The implementation and effectiveness of the EMP will be undertaken in conjunction with the Weekly Site Inspection Checklist undertaken by VEOLIA; this will determine whether the management plan has been properly maintained. External auditing may be commissioned when VEOLIA deems that procedures delineated in the EMP are not yielding a successful management outcome so that the plan can be reviewed and appropriately amended for a more relevant purpose.

#### 7.2 On-Going Applicability

The EMP should be updated in the following circumstances (if necessary):

- Subsequent to significant environmental incidents, such as a major breach in the containment system;
- Where maintenance of the EMP has indicated a need to improve performance in an identified area of environmental impact;
- At the completion of internal and/or external environmental audits;
- At the completed of Site Inspection Reports; and,
- At the completion of works which could have disturbed the capping layer.

VEOLIA will be required to commission an appropriate environmental professional agency to review and amend the EMP and ensure its conformance with statutory or regulatory instruments.

#### 7.3 Current Emergency Contact

In the case of an emergency, the contact details for VEOLIA at the date of this report are provided below:

NAME	POSITION	PHONE NUMBER	MOBILE NUMBER				
Emergency contact details are to be completed by an authorised VEOLIA representative							

FIGURE 1 – SITE LOCATION




FIGURE 2 – SITE DEVELOPMENT PLAN






FIGURE 3 – FILL DEPTHS AND MARKER LAYER







## **Capping Layer Survey Data**

Project Name		Veolia Banksmeadow				Project Number	727
Survey Number	Point Number	Easting	Northing	R.L of Capping Layer	Finish Surface Level	Depth of Clean Fill	Comments
Survey 1000	1001	335520.708	6241090.138	6.488	6.992	0.504	
Survey 1000	1002	335520.451	6241084.234	6.317	6.824	0.507	
Survey 1000	1003	335525.778	6241083.977	6.185	6.688	0.503	
Survey 1000	1004	335529.565	6241091.550	6.437	6.942	0.505	
Survey 2000	2000	335469.297	6241119.788	4.953	5.265	0.312	
Survey 2000	2001	335473.308	6241117.958	4.968	5.279	0.311	
Survey 2000	2002	335469.368	6241114.159	4.936	5.254	0.318	
Survey 2000	2003	335472.568	6241113.295	4.963	5.268	0.305	
Survey 2000	2004	335469.086	6241105.574	4.946	5.252	0.306	
Survey 2000	2005	335477.249	6241104.941	4.988	5.291	0.303	
Survey 2000	2006	335468.242	6241097.342	4.917	5.226	0.309	
Survey 2000	2007	335476.334	6241095.653	4.969	5.279	0.310	
Survey 2000	2008	335466.483	6241087.983	4.909	5.222	0.313	
Survey 2000	2009	335477.671	6241086.646	4.951	5.263	0.312	
Survey 2000	2010	335465.990	6241078.554	4.911	5.232	0.321	
Survey 2000	2011	335477.741	6241077.076	4.978	5.282	0.304	
Survey 2000	2012 2013	335465.498 335474.645	6241068.140 6241066.522	4.935 4.966	5.24 5.275	0.305 0.309	
Survey 2000	2013	335474.045	6241066.522	4.966	5.275	0.309	
C	2000	225464 272	(244422.5.5	F 404	- 0	0.710	
Survey 3000	3000	335464.378	6241128.848	5.184	5.9	0.716	
Survey 3000	3001	335465.044	6241136.038	5.094	5.802	0.708	
Survey 3000	3002	335465.664	6241141.597	5.15	5.853	0.703	
Survey 3000	3003	335466.239	6241147.868	5.192	5.798	0.606	
Survey 3000	3004	335466.836	6241153.680	5.159	5.864	0.705	
Survey 3000	3005	335467.594	6241159.101	5.202	5.912	0.710	
Survey 3000	3006	335468.076	6241162.915	5.397	6.099	0.702	
Survey 3000	3007	335473.635	6241165.763	5.61	6.112	0.502	
Survey 3000	3008	335479.470	6241169.875	5.53	6.035	0.505	
Survey 3000	3009	335477.219	6241173.183	5.528	6.029	0.501	
Survey 3000	3010	335474.302	6241170.771	5.582	6.086	0.504	
Survey 3000	3011	335469.891	6241167.210	5.654	6.158	0.504	
Survey 3000	3012	335468.375	6241171.575	5.629	6.129	0.500	
Survey 3000	3013 3014	335469.688 335474.062	6241178.152 6241177.367	5.561 5.526	6.063 6.034	0.502	
Survey 3000	5014	555474.002	0241177.307	5.520	0.034	0.508	
Survey 4000	4000	335465.225	6240987.188	4.596	5.104	0.508	
Survey 4000	4001	335464.822	6240983.435	4.562	5.068	0.506	
Survey 4000	4002	335470.893	6240987.440	4.667	5.171	0.504	
Survey 4000	4003	335470.691	6240982.453	4.703	5.209	0.506	
Survey 4000	4004	335475.754	6240986.861	4.807	5.314	0.507	
Survey 4000	4005	335475.528	6240981.999	4.799	5.305	0.506	
Survey 4000	4006	335480.389	6240981.319	4.841	5.349	0.508	
Survey 4000	4007	335484.697	6240980.916	4.927	5.43	0.503	
Survey 4000	4008	335489.256	6240980.362	5.037	5.541	0.504	
Survey 4000	4009	335493.161	6240979.455 6240979.480	5.19	5.699	0.509	
Survey 4000	4011 4012	335497.191		5.3	5.806 5.876	0.506	
Survey 4000 Survey 4000	4012 4013	335501.952 335505.882	6240977.868 6240977.137	5.369 5.519	6.027		
Survey 4000 Survey 4000	4013	335505.882	6240977.137	5.519	6.027	0.508	
Survey 4000 Survey 4000	4014	335501.631	6240981.080	5.539	6.014	0.506	
Survey 4000 Survey 4000	4015	335506.952	6240980.387	5.702	6.217	0.515	
Survey 4000 Survey 4000	4016	335508.432	6240984.890 6240984.858	5.702	6.078	0.515	
	+01/	JJJJU2.401	0240304.030	5.570	0.076	0.000	
Curran (2000	C000	225 450 575	(244000 010	4.000	4.007	0.201	
Survey 6000	6000	335450.575	6241000.916	4.606	4.907	0.301	
Survey 6000	6001	335455.738	6241000.617	4.696	4.996	0.300	
Survey 6000	6002	335452.221	6241009.372	4.7	4.999	0.299	
Survey 6000	6003	335456.337	6241009.372	4.7	5.008	0.308	
Survey 6000	6004 6005	335452.596	6241017.752	4.7	5	0.300	
Survey 6000	6005	335456.412	6241017.378	4.78	5.087	0.307	
Survey 6000	6006	335453.419	6241027.480 6241026.956	4.733	5.043	0.310	
Survey 6000	6007 6008	335457.834	6241026.956 6241037.881	4.767	5.076 5.006	0.309	
Survey 6000	6008 6009	335454.242	6241037.881	4.7 4.7	5.006	0.306	
Survey 6000		335458.806			5.008	0.308	
Survey 6000	6010 6011	335456.337	6241048.581 6241048 132	4.7		0.304	
Survey 6000	6011	335460.228	6241048.132	4.7	4.998 5.051	0.298	
Survey 6000	6012	335456.667	6241061.226	4.745	5.051	0.306	
Survey 6000	6013 6014	335461.450	6241060.671	4.79	5.085	0.295	
Survey 6000	6014 6015	335457.878	6241070.932	4.713	5.018	0.305	
Survey 6000	6015	335462.243	6241070.339	4.758	5.061	0.303	
Survey 6000	6016	335459.040	6241079.702	4.618	4.917	0.299	
Survey 6000	6017 6018	335463.376 335460.345	6241079.029 6241090.102	4.661 4.627	4.986 4.935	0.325 0.308	
Survey 6000		, <i></i>		0 6 1 1	// 11/L		

6 6000	6020	225460.000	C244000 442	4 74 4	5.040	0.005	
Survey 6000	6020	335460.808	6241099.112	4.714	5.019	0.305	
Survey 6000	6021	335465.552	6241098.709	4.754	5.055	0.301	
Survey 6000	6022	335462.225	6241108.447	4.821	5.13	0.309	
Survey 6000	6023	335466.264	6241108.034	4.841	5.148	0.307	
Survey 6000	6024	335462.932	6241116.234	4.932	5.241	0.309	
Survey 6000	6025	335466.706	6241116.117	4.945	5.246	0.301	
Survey 6000	6026	335463.871	6241123.189	5.373	5.681	0.308	
Survey 6000	6027	335467.774	6241121.973	5.556	5.856	0.300	
Survey 7000	7000	335460.407	6241018.286	4.909	5.209	0.300	
Survey 7000	7001	335468.645	6241017.497	4.915	5.228	0.313	
Survey 7000	7002	335470.047	6241027.399	4.982	5.294	0.312	
Survey 7000	7003	335460.495	6241029.240	4.908	5.214	0.306	
Survey 7000	7004	335460.894	6241037.900	4.945	5.247	0.302	
Survey 7000	7005	335471.843	6241036.879	4.935	5.25	0.315	
Survey 7000	7006	335473.333	6241048.414	4.99	5.299	0.309	
Survey 7000	7007	335462.819	6241049.530	4.92	5.231	0.311	
Survey 7000	7008	335464.346	6241058.987	4.927	5.229	0.302	
Survey 7000	7009	335474.273	6241057.988	4.93	5.234	0.304	
Survey 8000	8000	335505.142	6241003.910	6.066	6.371	0.305	
Survey 8000	8001	335509.673	6241002.562	6.011	6.311	0.300	
Survey 8000	8002	335506.677	6240997.394	5.9	6.2	0.300	
Survey 8000	8003	335502.483	6240999.079	5.9	6.203	0.303	
Survey 8000	8004	335503.831	6240994.062	5.802	6.101	0.299	
Survey 8000	8005	335503.682	6240991.590	5.781	6.09	0.309	
Survey 8000	8006	335508.887	6240990.804	5.939	6.248	0.309	
Survey 8000	8007	335508.287	6240986.310	5.82	6.209	0.389	
Survey 8000	8008	335502.371	6240987.022	5.757	6.065	0.308	
Survey 8000	8009	335495.631	6240987.883	5.534	5.842	0.308	
Survey 8000	8010	335496.043	6240991.590	5.627	5.937	0.310	
Survey 8000	8011	335494.208	6240993.837	5.681	5.982	0.301	
Survey 8000 Survey 8000	8011	335488.741	6240992.863	5.491	5.797	0.306	
Survey 8000	8012	335488.741	6240988.669	5.386	5.692	0.306	
Survey 8000	8013	335480.653	6240993.537	5.255	5.562	0.307	
Survey 8000 Survey 8000	8014	335480.578	6240988.295	5.158	5.464	0.306	
Survey 8000	8015	335480.690	6240984.700	5.171	5.472	0.301	
Survey 8000 Survey 8000	8010	335491.512	6240984.700	5.448	5.748	0.300	
· · · · · ·	8017	335473.800	6240994.399	5.082	5.386	0.300	
Survey 8000	8018	335473.800	6240994.399	4.93	5.233		
Survey 8000						0.303	
Survey 8000	8020	335465.600	6240995.222	4.881	5.185	0.304	
Survey 8000	8021	335465.375	6240990.504	4.728	5.028	0.300	
Survey 8000	8022	335460.919	6240985.786	4.432	4.938	0.506	
Survey 8000	8023	335453.505	6240986.835	4.529	4.837	0.308	
Survey 8000	8024	335457.474	6240989.943	4.547	4.854	0.307	
Survey 8000	8025	335450.921	6240992.564	4.511	4.815	0.304	
Survey 8000	8026	335456.426	6240995.222	4.629	4.929	0.300	
Survey 8000	8027	335450.584	6240996.870	4.556	4.862	0.306	





FIGURE 4 – SITE SURFACE FINISHES AND LAYOUT



# PLANTING SCHEDULE (BOTH DRAWINGS)

	BOTANIC NAME	TYPE 'A' AREA	TYPE 'B' AREA	COMMON NAME	MATURE HEIGHT	CONTAINER	APPROXIMATE
TREES		ESTIMATED QTYS	ESTIMATED QYTS		& SPREAD	SIZE	PLANT DENSITIES
BI	Banksia integrifolia	-	2	Coast Banksia	5.0 x 4.0m	45L	As shown
CG	Corymbia gummifera	-	1	Red Bloodwood	8.0 x 5.0m	25L	As shown
CM	Corymbia maculata	-	2	Spotted Gum	12.0 x 6.0m	25L	As shown
CA	Cupaniopsis anacardioides	-	2	Tuckeroo	6.0 x4.0mm	45L	As shown
MD	Melaleuca decora	-	4	White Feather Myrtle	8.0 x 4.0m	45L	As shown
SH	RUBS	(5 plants per 10m2)					
CAL	Correa alba	18	-	White Correa	1.0 x 1.0m	140mm	As shown
CC	Casuarina 'Cousin It'	38	-	Prostrate She Oak	1.0 x 1.0m	140mm	As shown
BE	Banksia ericifolia	-	7	Heath Banksia	3.0 x 2.0m	200mm	As shown
BS	Banksia spinulosa	-	11	Hairpin Banksia	1.5 x1.5m	200mm	As shown
CC	Callistemon citrinus	-	8	Crimson Bottlebrush	2.0 x 2.0m	200mm	As shown
KA	Kunzea ambigua	-	11	Tick Bush	2.0 x 2.0m	200mm	As shown
MN	Melaleuca nodosa	-	6	Ball Honeymyrtle	2.0 x 2.0m	200mm	As shown
WF	Westringia fruticosa	-	21	Coast Rosemary	1.5 x 1.5m	140mm	As shown
GR	OUNDCOVERS	(1 plant 1m <sup>2</sup> )					
CGL	Carpobrotus glaucescens	1,060 (366)	-	Coastal Pigface	N/A	Viro-Tube	1 / 1 sq metre
DC	Dianella congesta	-	365	Flax Lily	N/A	Viro-Tube	1/1 sq metre
FN	Ficinia nodosa	-	9	Club Rush	N/A	Viro-Tube	1/1 sq metre
LL	Lomandra longifolia	-	12	Mat Rush	N/A	Viro-Tube	1/1 sq metre
MP	Myoporum parvifolium	1,060 (366)	-	Creeping Boobialla	N/A	Viro-Tube	1 / 1 sq metre
Note	: Quantities in brackets de	enote Type 'A' Plants o	occurring on Drawing No	o 5114 - 02 only, to be plan	ted at the density of 2 pla	ants per sq.metro	9.

REFER DWG NO 5114 - 01 FOR LANDSCAPE SPECIFICATIONS

## NOTE:

PLANTS ARE LIVING ORGANISMS. IF THEY ARE MAINTAINED IN A HEALTHY CONDITION THEY SHALL CONTINUE TO GROW. IT WILL THEREFORE BE NECESSARY TO REGULARLY MONITOR THE GROWTH OF THE PLANTS SO THAT THEY CAN BE PRUNED OR OTHERWISE ATTENDED TO SO THAT THEY DO NOT OUTGROW THEIR ALLOTTED SPACE.

#### WRITTEN DIMENSIONS SHALL TAKE PRECEDENCE OVER SCALED MEASUREMENTS. ALL DIMENSIONS AND LEVELS SHALL BE VERIFIED BY CONTRACTOR ON SITE. CONTRATOR SHALL OBTAIN LANDSCAPE ARCHITECT'S WRITTEN APPROVAL OF INITIAL SETOUT PRIOR TO COMMENCEMENT OF WORK. IF IN DOUBT, CONTACT LANDSCAPE ARCHITECT.

ANY BATTER GREATER THAN 1 IN 3 SHALL BE STABILISED BY APPROVED GEOFABRIC OR OTHER EROSION CONTROL MEASURE, TO SATISFACTION OF LANDSCAPE ARCHITECT.

FINAL PLANT SIZES MAY BE ADJUSTED AS NECESSARY TO SUIT AVAILABILITY OF PLANT SPECIES AT TIME OF IMPLEMENTATION AND FINAL PROJECT BUDGET. SHOULD PROPOSED TREE LOCATION HAVE THE POTENTIAL TO INTERFERE WITH EXISTING OR PROPOSED UTILITIES, CONTRACTOR SHALL ADVISE LANDSCAPE

ARCHITECT AND AWAIT INSTRUCTIONS PRIOR TO PROCEEDING.

## LEGEND



HYBRID COUCH TURF TO OFFICE FRONTAGE AND NATURE STRIP. REFER SPECIFICATION.



TYPE 'A' VEGETATED BANK PLANTING. REFER PLANT SCHEDULE AND SPECIFICATIONS. DRIP IRRIGATION NOT REQUIRED.

TYPE 'B' PLANTING BEDS WITH DRIP IRRIGATION. REFER PLANT SCHEDULE AND SPECIFICATIONS

0 AND PROTECTED DURING

CONSTRUCTION PLANTING BED TIMBER EDGING AS SPECIFIED

			)		$\square$	
	MAGNE	TIC NOF	RTH	PROJEC	T NORTH	
E			R REDUCT		0	
D			UCTIONS		1	
B			ONSTRUC PPROVAL	TION	26	
A			ND DISCL	JSSION	15	
ISSUE	DESCRI	PTION			[	
Landscape Architects Environmental Planners Pool Designers 69 Christie Street, St Leonards NSW 2065 Phone (02) 9906 2727 Fax (02) 9906 4470 Email: design@peterglass.com.au						
PROJEC				the abrians cabice	INAL	
DRAWIN	G TITLE					
			PLA URR(	N - DUNDS	5	
SCALE DESIGNEL CHECKED DATE JOB NUM				00 @ A3		
DRAWIN	G NUMB	ER			ISSU	
5114	4 - 0	2			E	



	22.12.15 0 17.11.15 D 23.09.15 C 28.08.15 B 24.07.15 A	NOTE AND JOINT AMENDMENTS RE-ISSUED FOR CONSTRUCTION CERTIFICATE RE-ISSUED FOR CONSTRUCTION CERTIFICATE ISSUED FOR CONSTRUCTION CERTIFICATE	
		ACCESS RAMP JOINTS REMOVED - CLOUDED	
	<u>S OVER HV EASEMENT –</u> 280mm 'COMBI' SLAB U.N.O. 7 35kg/m <sup>3</sup> 0mm THICK TRO.7 MATERIAL RING DRAWING C56 FOR DETAILS 10 BE SL81 FABRIC	EXT. SLAB NOTE 280 THICK: 280 THICK: 280 THICK: EXTERNAL SLAB TO BE f'c - 32MPa DRAMIX 4D 65/60 BG AT SLAB TO BE LAID ON 50 REFER TO CIVIL ENGINEE SLAB REINFORCEMENT T 40mm TOP COVER <u>U.N.O.</u>	
Umm Umm Umm Umm	& CURRENT FINISH U.N.O. ON F E QUALITY E CEMENT ADMIXTURE SL NIL 4.	ARCHITECTURAL FINISHES AUSTRALIAN STANDARDS TEXTURED STEEL TROWEI ELEMENT SLUMP AGGREGAT PAVEMENT SLABS 80 20 MAXIMUM 56 DAY SHE	
EXTERNAL SLAB NOTES – EXTERNAL SLAB TO BE 32MPa, 180 TH REFER TO DETAIL ON DRAWING S52 SLAB TO BE LAID ON 400mm THICK DG SLAB REINFORCEMENT TO BE SL82 FAI 40mm TOP COVER <u>U.N.O.</u>	<b>NOTES</b> ALLS & F ALENT. C ENGINEI C ENGINEI BE COMP.	EXTERNAL S NUMM ABELFLEX ( NUMM ABELFLEX ( NUMM ABELFLEX ( NUMM ABELFLEX ( AR CHAIRS AT 6 AR CHAIRS AT 6	
BE ADDED TO CONCRETE ON SITE     Image: Display in the extent of concrete on site     Image: Display in the extent of concrete elimination is of concrete elimination of concrete elimination is of con	MIN. PAST TANK 40 TOP COVER NOTES GALV. ARMOURED DOWELLED JOINT ED CONSTRUCTION JOINT ED SOFT SAW CUT WELLED SAW CUT PANSION JOINT	EXTEND : SL92 FAE SL92 FAE SL72 FAE <u>LEGEND</u> <u>G-ADJ</u> <u>T-SC</u> <u>SC-DJ</u>	
	HICK SLAB	Room Pump	
<ul> <li>OFFICE LOCATION CONVENTIONAL JOINTED REFER TO S06 FOR JOINT LAYOUT</li> <li>HATCHED AREAS DENOTES LIGHT DUTY CONCRETE WET TOOLED JOINTS AT 2000 MAX. CTS. BUTT JOINTS 10mm AT EVERY 6000 CTS. REFER TO PEDESTRIAN SLAB DETAILS ON DRAWING S51. (b) (b) (b) (b) (b) (b) (b) (b) (b) (b)</li></ul>	OFFICE LOCATION     REFER TO SO6 FOF     WET TOOLED J     BUTT JOINTS 1     REFER TO PED     ON DRAWING S	KO KO KO	
O.S.D. TANK	$\begin{array}{c c} KO \\ \hline \\ $		





FIGURE 5 – SERVICES PLAN



DETAILS:DATE:BY:WORKSHOP ISSUE3/7/15BWISSUED FOR CC9/7/15BWPoles P6 & P7 added, Cable tray added21/8/15RRLIGHTING CHANGES26/8/15RRISSUED FOR CONSTRUCTION5/12/15RRAS-BUILT23/6/16BC REV:





PROJECT:		PROJECT NUMBER:	DRAWING NUMBER:	
BANKSMEADOW T	ERMINAL	LV	E-001	
CLIENT:		DRAWING NAME:		
LIPMAN PTY LTD		SITE SERV	ICES LAYOUT	
DRAWING STATUS:		SCALE:	DATE:	
CONSTRUCT	ION	1:500@E	31 23/06/16	
ALL WORKS TO FOLLOW WRITTEN DIMENSIONS, DO NOT SCALE DIMENSIONS				

**REVISION:** UMBER: AB 001 AYOUT DATE: DRAWN: 3/06/16 BC







FIGURE 6 – LANDSCAPING AREAS



**APPENDIX A** – VEOLIA ACKNOWLEDGEMENT LETTER



12 July 2016

To whom it may concern,

## Re: 34-36 McPherson St, Banksmeadow Site Audit Report

I refer to the email dated 7 July 2016 from Graeme Nyland to John Browne regarding the Site Audit Report for 34-36 McPherson St, Banksmeadow ("Land") In particular, I refer to points 20 (a), (g), 21 and 22 of this email.

Please be advised that the Long Term Environmental Management Plan prepared by DLA for the Land has been appended to the Soil, Water and Leachate Management Plan, which forms part of the Banksmeadow Transfer Terminal Operational Environmental Management Plan (OEMP). The OEMP was approved by the Secretary of the Department of Planning and Environment on 28 June 2016 and will form the basis for environmental controls to be implemented on site during operations.

Further to this commitment by Veolia, please be advised that the integrity of the cap on the Land will be inspected as part of the Weekly Site Inspection Checklist to ensure that the surface of the Land has not been disturbed or compromised.

Also, please be advised that if required, drawings showing services below the ground on the Land, which have been included in the Validation Report prepared by DLA will be registered with Dial Before You Dig.

I trust that this information provides sufficient confirmation that Veolia is committed to implementing measures to ensure that the integrity of the cap is maintained on the Land.


Yours sincerely,

CASh ....

Christine Hodgkiss General Manager – Strategic Planning, Development and Projects NSW Veolia Australia and New Zealand

APPENDIX B - UNEXPECTED FINDS PROTOCOL





# **Unexpected Finds Protocol**

34-36 McPherson Street Banksmeadow NSW 2019

Lipman Pty Ltd

July 2016



PROJECT NAME	Veolia Waste Transfer Facility - 34-36 McPherson Street, Banksmeadow, NSW.
PROJECT ID	DL3541
DOCUMENT CONTROL NUMBER	
PREPARED FOR	Lipman Pty Ltd
APPROVED FOR RELEASE BY	David Lane
DISCLAIMER AND COPYRIGHT	This report is subject to the copyright statement located at www.pacific-environment.com © Pacific Environment

DOCUMENT CONTROL					
VERSION	DATE	COMMENT	PREPARED BY	REVIEWED BY	
Version 1.0	13.07.16		John Browne	Anthony Richard	

DLA Environmental Services Pty Ltd: ABN 80 601 661 634

#### BRISBANE

Level 1, 59 Melbourne Street, South Brisbane, Qld 4101 PO Box 3306, South Brisbane, Qld 4101 Ph: +61 7 3004 6400 Ph: +61 7 3004 6400

Unit 1, 22 Varley Street Yeerongpilly, Qld 4105 Ph: +61 7 3004 6460

#### ADELAIDE

35 Edward Street, Norwood SA 5067 PO Box 3187, Norwood, SA 5067 Ph: +61 8 8332 0960 Fax: +61 7 3844 5858

#### PERTH

Level 1, Suite 3 34 Queen Street, Perth, WA 6000 Ph: +61 8 9481 4961 Fax: +61 2 9870 0999

#### SYDNEY

Suite 1, Level 1, 146 Arthur Street North Sydney, NSW 2060 Ph: +61 2 9870 0900 Fax: +61 2 9870 0999

Operations Pty Ltd ABN 86 127 101 642

#### DLA ENVIRONMENTAL SERVICES

Unit 3, 38 Leighton Place Hornsby, NSW 2077 Ph: +61 2 9476 1765 Fax: +61 2 9476 1557

42B Church St Maitland NSW 2320 Ph: +61 2 4933 0001

#### MELBOURNE

Level 10, 224 Queen Street Melbourne, Vic 3000 Ph: +61 3 9036 2637 Fax: +61 2 9870 0999



# **TABLE OF CONTENTS**

1.0	INTRODUCTION	. 3
2.0	TYPICAL FEATURES OF 'UNEXPECTED FINDS'	.4
3.0	IMPLEMENTATION OF THE PROTOCOL	. 5
3.1	General	. 5
3.2	Implementation Process	. 5
3.3	Notes	. 6
4.0	UNEXPECTED FINDS PROTOCOL FORM	. 8
5.0	UNEXPECTED FINDS REGISTER	.9



# **1.0 INTRODUCTION**

DLA Environmental Services (DLA) was commissioned by Lipman Pty Ltd to prepare an Unexpected Finds Protocol (UFP) for the property identified as:

### 34-36 McPherson Street, Banksmeadow NSW 2019 (the Site).

This UFP has been developed as part of the Long-term Environmental Management Plan for the Site. From the results of previous assessments, it was apparent that friable asbestos appeared to be present in the absence of significant bonded asbestos and was relatively widespread or randomly distributed in heterogeneous fill across the Site at low concentrations. DLA considered that asbestos at the Site will not pose a risk to human health as long as it remains undisturbed beneath the proposed development. The asbestos contaminated fill was management through capping and containing the Site with the new development.

If future works are to be undertaken on the Site which involve disturbance of the containment system and/or excavation of soil. It is thought prudent to implement a UFP to cover all possible potential contamination scenarios. Potential contamination on the Site which may exist outside the scope of the past environmental investigations will be managed through the following UFP.

# 2.0 TYPICAL FEATURES OF 'UNEXPECTED FINDS'

The main features to look for are:

- Material containing anthropogenic artefacts such as rubble, plastics, metal etc.;
- Material with an obvious unnatural odour, i.e. fuel, solvent, burnt odour;
- Material that is noticeably stained in colour;
- Asbestos or suspected asbestos containing material;
- Material with fibres visible; and,
- Any material that has evidently been dumped at the Site.



# **3.0 IMPLEMENTATION OF THE PROTOCOL**

## 3.1 General

Prior to the commencement of any excavation or construction works onsite, an occupational health and safety induction should be attended by all Site staff. The aim and importance of the UFP and how it is to be implemented should be discussed at this time. Responsibility for its implementation will be assigned to the Principal Contractor.

Monitoring of environmental issues will be undertaken on a daily basis. If an unexpected find is revealed during Site works, the following protocol is to be followed.

## **3.2 Implementation Process**

- **1.** Cease disturbance of the affected portion of the site and evacuate the immediate area.
- 2. Contact the Principal Contractor and the Contractors Environmental Representative (CER).
- **3.** Principal Contractor and CER to conduct an assessment of the location and extent of the unexpected find.
- **4.** High risk areas should be isolated and secured against unintended access.
- **5.** Temporary encapsulation (sealing) of the high risk area to ensure no airborne spread of contamination occurs may be appropriate. This may involve clean soil, plastic sheeting, etc.
- **6.** Dust should be prevented by wetting the soil and drainage controls should be arranged where there is a potential for runoff to occur (runoff should be minimised).
- 7. Warning signs should be placed in the vicinity.
- **8.** If the Principal Contractor and CER considers that the material warrants further investigation, the area is to be barricaded to provide an exclusion zone.
- **9.** If necessary, environmental controls should be established to minimise the potential for migration of contaminants from the impacted area.

- **10.** Principal Contractor to complete UFP form (refer to **Section 4.0**) and issue to all relevant stakeholders.
- **11.** Further visual assessment and sample collection and analysis undertaken by a qualified environmental consultant. If necessary, samples will be sent to a NATA registered laboratory.
- **12.** Evaluation of analytical data with respect to specific health screening levels to be undertaken. Contaminated soil incident report amended with final classification of soils, including whether the soils are suitable for the proposed land use, need to be remediated or disposed of offsite to a suitably licensed facility. If soils are suitable to remain on-site and/or the area is found to be clean, a work instruction will be provided by the CER to this effect. A waste classification letter must be provided prior to any offsite disposal.
- **13.** If the material is subsequently found to contain asbestos, an appropriately licensed contractor will be employed to remove it.
- **14.** Affected areas will be reopened for earthworks following a clearance of the location and issuance of a report by CER.

## 3.3 Notes

- **1.** Any suspected asbestos containing should be left in place and not disturbed. The CER will organise appropriate environmental professionals for further investigation purposes.
- **2.** It is essential that material of differing compositions not be mixed.
- **3.** All sampling for validation, waste classification or characterisation purposes will be carried out in accordance with the following documents:
  - Contaminated Sites: Sampling Design Guidelines (NSW EPA, 1995);
  - National Environment Protection (Assessment of Site Contamination) Amendment Measure 2013 (No.1) (NEPC, 2013);
  - Contaminated Sites: Guidelines for Assessing Service Station Sites (NSW EPA, 1994);
  - Waste Classification Guidelines (NSW EPA, 2014).

- 4. Any unexpected finds encountered should be listed on a UFP register, which should include the action taken and the status of the unexpected find. A suitable register is included in Section 5.0.
- 5. Once an unexpected find has been identified and a UFP form filled in the Principal Contractor and CER should liaise with the client as to the appropriate means of managing the situation. This should include discussions around the handling, treatment and disposal of material, OH&S considerations and how the affected area will be validated and reopened for works.
- 6. Prior to closing out an unexpected find it will be important to ensure the appropriate documentation is obtained, such as: photographs, the UFP form, waste classification letter(s) and a validation report or letter.
- 7. A UFP form should be completed on each day of the remedial works as part of the daily site records. This will ensure that the process is being undertaken even if no unexpected finds are encountered. The form should include the name, company and the position of the person undertaking the field observations.

## 4.0 UNEXPECTED FINDS PROTOCOL FORM

To be completed by the Site Controller/Environmental Representative

SITE:			
PERSONNEL ON-SITE:			
DATE:			
DAILY SUMMARY:			
1.	Suspect material encountered during daily activities: (if YES, compete 2 to 5)	YES	NO
2.	CER contacted:	YES	NO
3.	UFP Reference Number (label occurrences sequentially 1, 2, 3, etc.).		
DESCRIPTION OF MATERIA	L ENCOUNTERED:		
4.	Asbestos or suspected ACM present:	YES	NO
5.	Brief written description of material:		
6.	Material isolated:	YES	NO
7.	Location of contaminated material (incl. field sketch/ma	p if required):	
8.	Photographs taken:	YES	NO
NAME:	SIGNATURE:		



## **5.0 UNEXPECTED FINDS REGISTER**

	UNEXPECTED FINDS REGISTER					
UFP No.	Date Found	Suspect Material	Description	Recorded on UFP Form	Action Taken	Status
				YES NO		
				YES NO		
				YES NO		
				YES NO		
				YES NO		
				YES NO		




Page: Page 36 of 36 Document: PLA-NSW-XXX-XXX-1 Date: 23.06.2016

PLAN

Soil, Water and Leachate Management

Appendix F Groundwater wells locations





Site Layout & Well Network (Feb 2017)

Veolia- McPherson St, Banksmeadow